



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS FSI DSG SPORT
Colour	Black
Year of manufacture	-
Top speed	142 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	280 Nm at 5.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.5 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-13
Pictures	21
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #17	2023-11-23 15:22
MOT test number	902747658798
Result	✓ Passed
Next expiry date	2024-11-22

MOT #16	2022-05-26 10:54
MOT test number	463746466675
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Registration plate deteriorated but not likely to be misread FRONT & REAR (0.1 (b))

MOT #15	2021-05-26 12:20
MOT test number	896705607527
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2021-05-26 08:28

MOT test number

777062581289

Result

✗ Failed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
- MAJOR** Nearside Front Direction indicator not working Mirror (4.4.1 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn Rear (5.3.4 (a) (i))

MOT #13

2020-03-23 17:34

MOT test number

193320169196

Result

✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12

2019-03-16 17:22

MOT test number

594813025472

Result

✓ Passed

- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement n/s-o/s (5.3.4 (a) (i))
- Advice** Under trays fitted and engine covers fitted

MOT #11

2018-03-26 15:58

MOT test number

488050561388

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #10**

2018-03-26 11:29

MOT test number

456973678894

Result**✗ Failed****Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9**

2017-03-14 10:10

MOT test number

952553413234

Result**✓ Passed****MOT #8**

2017-03-13 12:23

MOT test number

614407339476

Result**✗ Failed****Fail** Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Front Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front front brake excessively fluctuating (3.7.B.3)**MOT #7**

2016-03-29 13:25

MOT test number

411646230151

Result**✓ Passed****Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt outer (2.5.C.1a)

**MOT #6** 2015-03-18 15:54**MOT test number** 285027175096**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-03-17 16:23**MOT test number** 706216075059**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2014-03-18 14:53**MOT test number** 939127174016**Result** ✓ Passed**Advice** Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #3** 2013-03-08 14:54**MOT test number** 138457263012**Result** ✓ Passed**MOT #2** 2012-01-19 11:33**MOT test number** 955239912003**Result** ✓ Passed



MOT #1	2012-01-17 15:31
MOT test number	829837612013
Result	✗ Failed
Fail	Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	KT58BVX
Plate since	2019-06-29
Current registration	KT58BVX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-11-17
Last registration	2023-11-23
Complete history	See info



Registration #1	2008-11-17	28 mi
Registration #2	2012-01-17	45.624 mi
Registration #3	2012-01-19	45.628 mi
Registration #4	2013-03-08	54.704 mi
Registration #5	2014-03-18	65.002 mi
Registration #6	2015-03-17	76.234 mi
Registration #7	2015-03-18	76.285 mi
Registration #8	2016-03-29	89.936 mi
Registration #9	2017-03-13	99.165 mi
Registration #10	2017-03-14	99.171 mi
Registration #11	2018-03-20	110.307 mi
Registration #12	2018-03-20	110.317 mi
Registration #13	2018-03-20	110.327 mi
Registration #14	2018-03-20	110.337 mi
Registration #15	2018-03-20	110.347 mi
Registration #16	2018-03-20	110.357 mi
Registration #17	2018-03-20	110.367 mi
Registration #18	2018-03-20	110.377 mi
Registration #19	2018-03-20	110.387 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1557 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BWA251255