





## General information

| Make                | LAND ROVER        |
|---------------------|-------------------|
| Model               | FREELANDER TD4 XS |
| Colour              | Black             |
| Year of manufacture | 2011              |
| Top speed           | 112 mph           |
| 0 - 100 km/h        | 11.7 seconds      |
| 0 - 60 mph          | 10.9 seconds      |
| Gearbox             | 6 speed Manual    |

## Engine & fuel consumption

| Power                   | 110 kW / 150 HP / 150 BHP |
|-------------------------|---------------------------|
| Max. torque             | 420 Nm at 1.750 rpm       |
| Engine capacity         | 2.179 cc                  |
| Cylinders               | 4                         |
| Fuel type               | Diesel                    |
| Consumption city        | 38.2 mpg                  |
| Consumption extra urban | 50.4 mpg                  |
| Consumption combined    | 45.6 mpg                  |
| CO2 emission            | 165 g/km                  |
| CO2 label               | G                         |





AV61CNJ report date: 2024-03-29

| i <b>ntry 1</b><br>Date  | 2021-10-0   | )2         |  |
|--|---|------------|--|
| Pictures   | 5   |            |  |
| _isting price  | View repo   | <u>ort</u> |  |
| Video viewing         Book a video viewing with one of our team.         Book a video viewing with one of our team.         Contract of your own home. | <b>Circle &amp; Deliver</b><br>Complete your deal online or by phone.<br>There are range for the santilead weblick to be deleveed to you. |            |  |



# MOT history

| MOT expiry date    | 2024-10-17 |
|--------------------|------------|
| MOT pass rate      | 92 %       |
| MOT passed         | 11         |
| Failed MOT tests   | 1          |
| Total advice items | 4          |
| Total items failed | 0          |

| MOT #12          | 2023-10-09 14:42 |
|------------------|------------------|
| MOT test number  | 463166480268     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-10-17       |

| MOT #11  |   | 2022-10-11 08:54 |
|----------|---|------------------|
| MOT test | number  | 906433343711     |
| Result   |   | ✓ Passed         |
| Advice   | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
| Advice   | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |

| MOT #10  | 2021-10-18 13:24 |
|--|------------------|
| MOT test number  | 914907786595     |
| Result   | ✓ Passed         |
| Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) |                  |

| МОТ #9          | 2021-08-03 07:25 |
|-----------------|------------------|
| MOT test number | 528565421239     |
| Result          | ✓ Passed         |





| MOT #8             |  | 2021-08-02 13:29                 |
|--------------------|--|----------------------------------|
| MOT test           | number   | 660844989057                     |
| Result             |  | 🗙 Failed                         |
| MAJOR              | Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i)) |                                  |
| MOT #7             |  | 2020-08-06 10:45                 |
| MOT test           | number   | 124768791621                     |
| Result             |  | ✓ Passed                         |
|                    |  |                                  |
| MOT #6             |  | 2019-07-29 08:23                 |
| MOT test           | number   | 748222582747                     |
| Result             |  | ✓ Passed                         |
|                    |  |                                  |
| MOT #5             |  | 2018-08-07 15:35                 |
| MOT test           | number   | 376386991761                     |
| Result             |  | ✓ Passed                         |
| MOT #4             |  | 2017 00 12 10 40                 |
| MOT #4<br>MOT test | number   | 2017-09-12 10:48<br>869897540363 |
| Result             | number   | ✓ Passed                         |
| Result             |  | V rasseu                         |
| MOT #3             |  | 2016-09-06 07:47                 |
| MOT test           | number   | 369934893389                     |
| Result             |  | ✓ Passed                         |
|                    |  |                                  |
| MOT #2             |  | 2015-09-10 09:14                 |
| MOT test           | number   | 549966792128                     |
| -                  |  |                                  |

Result

✓ Passed





| MOT #1          | 2014-09-18 09:51 |
|-----------------|------------------|
| MOT test number | 846961464255     |
| Result          | ✓ Passed         |



Tax & MOT check

| <b>Tax due:</b><br>1 October 2024 | ✓<br>Taxed | <b>Expires:</b><br>17 October 2024 | мот                   |
|-----------------------------------|------------|------------------------------------|-----------------------|
| Tax status                        |            |                                    | Valid until 1 October |
| Days left                         |            |                                    | 156                   |
| MOT expiry date                   |            |                                    | 17 October 2024       |
| Full MOT history                  |            |                                    | See MOT history       |
| Tax calculation                   |            |                                    |                       |

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | G          |
| Single payment (12 months)              | £ 240,00,- |
| Single six month payment                | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |





### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |        |
|----------|--------|
| Date     |        |
| Category | AAMP   |
| Туре     |        |
| Damage 2 | AMPLE  |
| Date     |        |
|          | MPLE . |
| Category | ter .  |
| Туре     |        |

#### Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and the second |             |
|---|-------------|
| ***********   |             |
| ********  |             |
| *******   |             |
| **********  |             |
| ********  |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this LAND ROVER had different number plates.   |             |





### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info  $\rightarrow$ 





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 14         |
| First mileage registration | 2011-09-22 |
| Last registration          | 2023-10-09 |
| Complete history           | See info   |



| Registration #1   | 2011-09-22 | 15 mi  |
|---|------------|--|
| Registration #2   | 2014-09-18 | 18.184 mi  |
| Registration #3   | 2015-09-10 | 24.551 mi  |
| Registration #4   | 2016-09-06 | 30.887 mi  |
| Registration #5   | 2017-09-12 | 38.525 mi  |
| Registration #6   | 2018-08-07 | 44.645 mi  |
| Registration #7   | 2019-07-29 | 55.331 mi  |
|   |            |  |
| Registration #8   |            | 11.317 est   |
| Registration #8<br>Registration #9                      |            | 11.517 es  |
| -   |            | 01.000 est<br>01.000 est<br>01.000 est                               |
| Registration #9   |            | 0.000 es   |
| Registration #9<br>Registration #10                     |            | 0.000 es   |
| Registration #9<br>Registration #10<br>Registration #11 |            | 0.000 es<br>0.000 es<br>0.000 es<br>0.000 es<br>0.000 es<br>0.000 es |

More info  $\rightarrow$ 





Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight                                    |                          |
|--|--------------------------|
| Width  | 2180 mm                  |
| Height   | 1740 mm                  |
| Length   | 4500 mm                  |
| Wheel base   | 2660 mm                  |
| Kerb weight  | 1770 kg                  |
|  |                          |
| Additional information                                 |                          |
| Additional information Fuel tank capacity              | 68 I                     |
|  | 68 l<br>Direct Injection |
| Fuel tank capacity                                     |                          |
| Fuel tank capacity<br>Fuel delivery                    | Direct Injection         |
| Fuel tank capacity<br>Fuel delivery<br>Number of doors | Direct Injection<br>5    |