



report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA 12V EXPRESSION TWINPORT
Colour	Red
Year of manufacture	2005
Top speed	88 mph
0 - 60 mph	16.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	58 BHP
Max. torque	85 Nm at 3.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-14
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-13
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	26
Total items failed	4

MOT #19	2024-04-02 15:08
MOT test number	347215359483
Result	✓ Passed
Next expiry date	2025-04-13
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #18	2023-04-06 08:50
MOT test number	883035484515
Result	✓ Passed
Advice	Offside Play in steering rack inner joint(s)
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Play in steering rack inner joint(s)
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #17** 2022-03-29 12:19**MOT test number** 505433538899**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #16** 2021-04-14 13:54**MOT test number** 388651574762**Result** ✓ Passed**Advice** Nearside Front Upper Macpherson strut mounting damaged but not seriously weakened slight play (5.3.3 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #15** 2020-05-18 12:16**MOT test number** 612793224732**Result** ✓ Passed**MOT #14** 2019-05-16 12:52**MOT test number** 953579510299**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))

**MOT #13** 2019-05-16 10:13**MOT test number** 564548888282**Result** ✗ Failed

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure badly perished in tread (5.2.3 (d) (ii))

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure badly perished in tread (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))

MOT #12 2017-10-05 08:54**MOT test number** 279807974889**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit Uneven wear to edges (4.1.E.1)

MOT #11 2016-08-05 12:01**MOT test number** 207772638352**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre perished

MOT #10 2015-07-15 10:51**MOT test number** 197666995125**Result** ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2014-07-29 11:22**MOT test number** 917540614258**Result** ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2013-07-25 14:02**MOT test number** 325816903207**Result** ✓ Passed**MOT #7** 2012-08-09 10:46**MOT test number** 705892922275**Result** ✓ Passed**MOT #6** 2011-08-02 15:29**MOT test number** 318474211210**Result** ✓ Passed**MOT #5** 2010-08-02 16:47**MOT test number** 931444310263**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2010-08-02 15:44**MOT test number** 533754610246**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2009-07-22 11:53**MOT test number** 264123009218**Result** ✓ Passed**Notice** Not checked n/s/r seat belt due to child seat being fitted.



MOT #2	2008-07-29 09:58
MOT test number	101451118246
Result	✓ Passed

MOT #1	2008-07-29 09:58
MOT test number	874301718278
Result	✗ Failed

Pass with rectification

 Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
13 April 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	13 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	WP05XTG
Plate since	2024-03-29
Current registration	WP05XTG
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-07-29
Last registration	2024-04-02
Complete history	See info



Registration #1	2005-07-29	27 mi
Registration #2	2008-07-29	5.971 mi
Registration #3	2009-07-22	7.810 mi
Registration #4	2010-08-02	11.512 mi
Registration #5	2010-08-02	11.512 mi
Registration #6	2011-08-02	14.698 mi
Registration #7	2012-08-09	17.902 mi
Registration #8	2013-07-25	19.484 mi
Registration #9	2014-07-29	21.121 mi
Registration #10	2015-07-15	27.001 mi
Registration #11	2016-07-29	28.277 mi
Registration #12	2017-07-29	29.553 mi
Registration #13	2018-07-29	30.829 mi
Registration #14	2019-07-29	32.105 mi
Registration #15	2020-07-29	33.381 mi
Registration #16	2021-07-29	34.657 mi
Registration #17	2022-07-29	35.933 mi
Registration #18	2023-07-29	37.209 mi
Registration #19	2024-04-02	38.485 mi
Registration #20	2024-04-02	38.485 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1940 mm
Height	1660 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	965 kg
Max. allowed weight	1435 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	19EH5413