



GMO2MGO

report date: 2024-03-29

General information

Make	NISSAN
Model	ELGRAND
Colour	White
Year of manufacture	2002
Gearbox	-

Engine & fuel consumption

Engine capacity	3.490 cc
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-16
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-03-06
MOT pass rate	50 %
MOT passed	8
Failed MOT tests	8
Total advice items	39
Total items failed	18

MOT #16 2024-04-16 11:23

MOT test number 109030381458

Result ✗ Failed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Nearside Rear Upper Suspension arm pin or bush excessively worn both (5.3.4 (a) (i))
- Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Rear Tyre(s) with different structures are fitted across the same axle (5.2.3 (c))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #15 2023-03-07 10:52

MOT test number 804608135717

Result ✓ Passed

- Advice** Engine cover/under tray fitted

**MOT #14** 2023-02-27 12:57**MOT test number** 152625644054**Result** ✗ Failed**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Engine cover/under tray fitted**MOT #13** 2022-02-21 13:19**MOT test number** 705062567024**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2022-02-21 10:42**MOT test number** 334615807755**Result** ✗ Failed**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2021-02-04 10:17**MOT test number** 998180488977**Result** ✓ Passed

**MOT #10** 2021-02-04 10:17**MOT test number** 393674528409**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**MOT #9** 2020-02-04 13:04**MOT test number** 191041458964**Result** ✓ Passed**MOT #8** 2020-02-04 09:24**MOT test number** 578258346583**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #7** 2019-02-23 12:39**MOT test number** 511287412878**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6** 2019-02-21 10:08**MOT test number** 824741570972**Result** ✗ Failed

- Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Minor** Headlamp lens slightly defective nearside/offside (4.1.1 (b) (i))
- Fail** Offside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #5 2018-01-30 13:20**MOT test number** 490929683116**Result** ✓ Passed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)
- Advice** Nearside Front Road wheel slightly damaged inside (4.2.A.1a)
- Advice** Offside Rear Road wheel slightly damaged inside (4.2.A.1a)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)
- Advice** Nearside Rear Road wheel slightly damaged inside (4.2.A.1a)

**MOT #4**

2018-01-26 11:23

MOT test number

692670915371

Result**✗ Failed**

- Advice** Offside Rear Inner Road wheel slightly damaged (4.2.A.1a)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)
- Advice** Offside Rear tyre flat and has been driven flat . sidewall damaged .
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)
- Fail** Rear Brake performance not tested brakes not tested due to flat tyre (3.7.A.1)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3

2017-01-19 10:01

MOT test number

821185989711

Result**✓ Passed**

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Rear Tyre worn close to the legal limit nearside/offside have low edges (4.1.E.1)
- Advice** Front Tyre worn close to the legal limit nearside/offside have low edges (4.1.E.1)

MOT #2

2016-01-27 09:51

MOT test number

757253151110

Result**✓ Passed**



MOT #1	2016-01-25 09:51
MOT test number	964108412502
Result	✗ Failed
Fail	Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt both (2.4.G.2)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Fail	Nearside Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)



Tax & MOT check

✕
Untaxed

Tax expired:
1 April 2024

✕
MOT

Expired:
6 March 2024

Tax status

Expired at 1 April 2024

Days left

28 days too late

MOT expiry date

6 March 2024

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2016-01-25
Last registration	2024-04-16
Complete history	See info



Registration #1	2016-01-25	68.807 mi
Registration #2	2016-01-27	68.817 mi
Registration #3	2017-01-19	72.577 mi
Registration #4	2018-01-26	75.487 mi
Registration #5	2018-01-30	75.490 mi
Registration #6	2019-02-21	77.769 mi
Registration #7	2019-02-23	77.782 mi
Registration #8	2020-02-04	80.154 mi
Registration #9	2020-02-04	80.165 mi
Registration #10	2020-02-04	80.165 mi
Registration #11	2020-02-04	80.165 mi
Registration #12	2020-02-04	80.165 mi
Registration #13	2020-02-04	80.165 mi
Registration #14	2020-02-04	80.165 mi
Registration #15	2020-02-04	80.165 mi
Registration #16	2020-02-04	80.165 mi
Registration #17	2020-02-04	80.165 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Additional information

Number of seats	7
Engine number	NOT KNOWN