



report date: 2024-03-29

General information

Make	NISSAN
Model	PATHFINDER DCI AVENTURA
Colour	Grey
Year of manufacture	2006
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	172 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.4 mpg
Consumption extra urban	34.0 mpg
Consumption combined	28.0 mpg
CO2 emission	267 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-08-08
Pictures	27
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-02-04
-----------------	------------

MOT pass rate	68 %
---------------	------

MOT passed	13
------------	----

Failed MOT tests	6
------------------	---

Total advice items	27
--------------------	----

Total items failed	15
--------------------	----

MOT #19	2022-02-05 09:25
---------	------------------

MOT test number	702645186548
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2023-02-04
------------------	------------

Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
--------	---

Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
--------	--

Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
--------	--

MOT #18	2022-02-01 09:11
---------	------------------

MOT test number	187648910149
-----------------	--------------

Result	✗ Failed
--------	----------

Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
--------	--

Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
--------	--

Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
------	--

Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
--------	---

Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
------	--

**MOT #17** 2020-12-15 14:40**MOT test number** 568727822975**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #16 2020-12-15 14:40**MOT test number** 431773449279**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2019-12-13 14:19**MOT test number** 452830032092**Result** ✓ Passed

- Advice** Both front tyres worn on edges

**MOT #14** 2019-12-12 11:04**MOT test number** 185919052138**Result** ✗ Failed

- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Driver's door cannot be opened from inside the vehicle (6.2.3 (a))
- Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Both front tyres worn on edges

MOT #13 2018-12-12 10:57**MOT test number** 228374477512**Result** ✓ Passed**MOT #12** 2017-12-04 17:00**MOT test number** 397599122306**Result** ✓ Passed**MOT #11** 2017-12-01 09:58**MOT test number** 939443653972**Result** ✗ Failed

- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #10** 2016-12-14 16:53**MOT test number** 638315005777**Result** ✓ Passed**MOT #9** 2016-12-08 11:35**MOT test number** 952192345752**Result** ✗ Failed**Fail** Offside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**MOT #8** 2016-03-22 11:46**MOT test number** 282727766902**Result** ✓ Passed**MOT #7** 2016-03-17 15:16**MOT test number** 335230550426**Result** ✗ Failed**Fail** Nearside Front Headlamp cleaning device inoperative (1.7.2)**Fail** Offside Front Headlamp cleaning device inoperative (1.7.2)**MOT #6** 2015-03-14 12:03**MOT test number** 575333375027**Result** ✓ Passed**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1a)**Notice** Child seat fitted NSR seatbelt not checked**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)

**MOT #5** 2014-03-17 13:45**MOT test number** 358206174006**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #4** 2013-03-13 18:10**MOT test number** 607112873027**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #3** 2012-02-21 15:11**MOT test number** 245252852076**Result** ✓ Passed**MOT #2** 2010-11-05 13:49**MOT test number** 473019000392**Result** ✓ Passed**Notice** Off side rear door handle broken**MOT #1** 2009-11-06 11:33**MOT test number** 711510619377**Result** ✓ Passed



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-10-12
Last registration	2022-02-05
Complete history	See info



Registration #1	2006-10-12	19 mi
Registration #2	2009-11-06	15.350 mi
Registration #3	2010-11-05	27.373 mi
Registration #4	2012-02-21	42.225 mi
Registration #5	2013-03-13	47.340 mi
Registration #6	2014-03-17	56.636 mi
Registration #7	2015-03-14	68.952 mi
Registration #8	2016-03-17	79.081 mi
Registration #9	2016-03-22	79.137 mi
Registration #10	2016-12-08	85.915 mi
Registration #11	2016-12-14	85.915 mi
Registration #12	2016-12-14	85.915 mi
Registration #13	2016-12-14	85.915 mi
Registration #14	2016-12-14	85.915 mi
Registration #15	2016-12-14	85.915 mi
Registration #16	2016-12-14	85.915 mi
Registration #17	2016-12-14	85.915 mi
Registration #18	2016-12-14	85.915 mi
Registration #19	2016-12-14	85.915 mi
Registration #20	2016-12-14	85.915 mi
Registration #21	2016-12-14	85.915 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).


More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1850 mm
Height	1783 mm
Length	4740 mm
Wheel base	2850 mm
Kerb weight	2195 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	750331