

## **\$** SUZUKI



## General information

MakeSUZUKIModelALTO SZColourRedYear of manufacture2015Top speed96 mph0 - 60 mph13.5 secondsGearbox5 speed Manual			
ColourRedYear of manufacture2015Top speed96 mph0 - 60 mph13.5 seconds	Make	SUZUKI	
Year of manufacture         2015           Top speed         96 mph           0 - 60 mph         13.5 seconds	Model	ALTO SZ	
Top speed         96 mph           0 - 60 mph         13.5 seconds	Colour	Red	
<b>0 - 60 mph</b> 13.5 seconds	Year of manufacture	2015	
	Top speed	96 mph	
Gearbox 5 speed Manual	0 - 60 mph	13.5 seconds	
	Gearbox	5 speed Manual	

## Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	А







# Internet history

Entry 1

Date Pictures 2021-02-04

10

Listing price

View report





source: autoonline.co.uk



# MOT history

MOT expiry date	2025-03-25
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #8	2024-03-26 11:02
MOT test number	354363234948
Result	✓ Passed
Next expiry date 2025-	
Advice Rear Coil spring corroded both (5.3.1 (b) (i))	
Advice Front Coil spring corroded both (5.3.1 (b) (i))	

MOT #7	2023-02-23 17:38
MOT test number	310113252604
Result	✓ Passed

MOT #6	2023-02-23 13:55
MOT test number	748564815017
Result	🗙 Failed
Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	

MOT #5	2022-02-28 12:01	
MOT test number	596840243465	
Result	✓ Passed	
<b>Advice</b> Offside Front Suspension arm pin or bush worn but not resulting in excessive movement back bush (5.3.4 (a) (i))		





MOT #4	2021-02-08 12:14
MOT test number	381660744306
Result	✓ Passed
MOT #3	2020-02-27 09:43
MOT test number	782923854019
Result	✓ Passed
Advice Offside Front Suspension arm pin or bush worn but n (i))	ot resulting in excessive movement (5.3.4 (a)
Advice Nearside Front Suspension arm pin or bush worn but (a) (i))	not resulting in excessive movement (5.3.4
Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c	) (i))

MOT #2	2019-03-01 09:44
MOT test	<b>number</b> 726971982384
Result	✓ Passed
<b>Advice</b> (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

MOT #1	2018-03-02 10:02
MOT test	number 682375633155
Result	✓ Passed
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)
Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
<b>Advice</b> (2.4.G.2)	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement



Tax & MOT check

<b>Tax due:</b> 1 May 2025	✓ Taxed	<b>Expires:</b> 25 March 2025	✓ MOT
Tax status			Valid until 1 May
Days left			366
MOT expiry date			25 March 2025
Full MOT history			See MOT history
Tax calculation			
Vehicle class		48	

Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





### Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	E Store
Date	1. E
Category	amt
Туре	

#### Extra SUZUKI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
*************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this SUZUKI had different number plat	es.
Number of plates	9
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-03-04
Last registration	2024-03-26
Complete history	See info



Registration #1	2015-03-04	15 mi
Registration #2	2018-03-02	43.605 mi
Registration #3	2019-03-01	56.305 mi
Registration #4	2020-02-27	67.363 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		10.300 est

More info >





# Safety ratings

NCAP rating	****
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Max. allowed weight	1250 kg
Additional information	
Additional information Fuel tank capacity	35 I
	35 I Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5