



NX08UEK

report date: 2024-03-28

General information

Make	MAZDA
Model	5 TS2
Colour	Grey
Year of manufacture	2008
Top speed	113 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	182 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-11-28
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-01-26
MOT pass rate	57 %
MOT passed	13
Failed MOT tests	10
Total advice items	43
Total items failed	21

MOT #23	2023-01-27 10:31
MOT test number	519684938344
Result	✓ Passed
Next expiry date	2024-01-26
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #22	2022-01-20 10:35
MOT test number	231111456697
Result	✓ Passed

MOT #21	2022-01-19 09:01
MOT test number	723683370362
Result	✗ Failed
DANGEROUS	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
MAJOR	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
DANGEROUS	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))



MOT #20	2021-02-25 16:32
MOT test number	826953449840
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #19	2021-02-22 14:09
MOT test number	936035766928
Result	✗ Failed
MAJOR	Exhaust has a major leak of exhaust gases Pipe from Centre silencer to Rear (Blowing in a few places) (6.1.2 (a))
DANGEROUS	Offside Rear Inner Tyre has ply or cords exposed Inner edge (5.2.3 (d) (ii))
Minor	Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
MAJOR	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Minor	Nearside Rear Rear reflector insecure (4.8.1 (b) (i))

MOT #18	2020-05-12 08:18
MOT test number	666391467992
Result	✓ Passed

MOT #17	2020-05-12 08:18
MOT test number	833946521322
Result	✗ Failed
Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #16	2019-05-02 07:03
MOT test number	956574126560
Result	✓ Passed

**MOT #15** 2019-05-02 07:03**MOT test number** 374352315942**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**MOT #14** 2018-05-10 12:49**MOT test number** 163506993323**Result** ✓ Passed**Advice** Front Items removed from driver's view prior to test**MOT #13** 2017-05-18 09:59**MOT test number** 668769774811**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**Advice** Child seat fitted n/s rear belt not tested

**MOT #12**

2017-05-17 10:07

MOT test number

743633047108

Result**✗ Failed****Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Engine has no oil when checked.engine has oil leak**Fail** Front Suspension arm rubber bush deteriorated resulting in excessive movement both arms (2.4.G.2)**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**Advice** Child seat fitted n/s rear belt not tested**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #11**

2016-05-27 14:17

MOT test number

345911304062

Result**✓ Passed****MOT #10**

2016-05-25 12:04

MOT test number

276302609960

Result**✗ Failed****Fail** Nearside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Offside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

**MOT #9**

2015-05-30 12:41

MOT test number

928480655179

Result

✓ Passed

Advice

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #8

2015-05-30 11:03

MOT test number

378700555143

Result

✗ Failed

Fail

Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #7

2014-02-04 12:09

MOT test number

368345834059

Result

✓ Passed

Advice

Shock absorber has a light misting of oil (2.7.3)

MOT #6

2014-02-04 12:09

MOT test number

355555134022

Result

✗ Failed

Advice

Shock absorber has a light misting of oil (2.7.3)

Pass with rectification

Nearside Headlamp aim too low (1.8)

**MOT #5** 2013-02-22 10:59**MOT test number** 819463553097**Result** ✓ Passed**Advice** Offside Outer Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** 205/55/16**Notice** Both rear tyres perished**MOT #4** 2013-02-22 09:21**MOT test number** 806063453067**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Outer Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**Notice** 205/55/16**Fail** Rear registration plate character(s) incorrectly spaced (6.3.4a)**Fail** Rear registration plate margin less than the minimum requirement (6.3.4g)**Notice** Both rear tyres perished**Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)**Fail** Front registration plate margin less than the minimum requirement (6.3.4g)**MOT #3** 2012-02-13 09:05**MOT test number** 879074342051**Result** ✓ Passed

**MOT #2** 2011-03-01 15:26**MOT test number** 306980861096**Result** ✓ Passed**Notice** Nearside rear + offside rear seat belts not fully inspected due to child seats fitted**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2011-03-01 13:58**MOT test number** 339620561069**Result** ✗ Failed**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Nearside rear + offside rear seat belts not fully inspected due to child seats fitted**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Fail** Rear registration plate insecure (6.3.1b)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✗
MOT

Expired:
26 January 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	26 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	NX08UEK
Plate since	2019-09-28
Current registration	NX08UEK
Plate since	2019-09-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2008-03-03
Last registration	2023-01-27
Complete history	See info



Registration #1	2008-03-03	24 mi
Registration #2	2011-03-01	24.871 mi
Registration #3	2011-03-01	24.871 mi
Registration #4	2012-02-13	35.601 mi
Registration #5	2013-02-22	47.211 mi
Registration #6	2013-02-22	47.211 mi
Registration #7	2014-02-04	60.738 mi
Registration #8	2015-05-30	76.366 mi
Registration #9	2015-05-30	76.366 mi
Registration #10	2016-05-25	85.330 mi
Registration #11	2016-05-27	85.330 mi
Registration #12	2017-05-17	94.375 mi
Registration #13	2018-05-20	103.319 mi
Registration #14	2018-05-20	103.319 mi
Registration #15	2019-05-20	112.263 mi
Registration #16	2019-05-20	112.263 mi
Registration #17	2020-05-20	121.207 mi
Registration #18	2020-05-20	121.207 mi
Registration #19	2021-05-20	130.151 mi
Registration #20	2021-05-20	130.151 mi
Registration #21	2022-05-20	139.095 mi
Registration #22	2022-05-20	139.095 mi
Registration #23	2023-01-27	148.039 mi
Registration #24	2023-01-27	148.039 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1615 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1400 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	L8 20227673