



TOYOTA




report date: 2024-03-29

General information

| | |
|---------------------|-----------------------|
| Make | TOYOTA |
| Model | COROLLA VERSO D-4D SR |
| Colour | Black |
| Year of manufacture | 2007 |
| Top speed | 122 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 134 BHP |
| Max. torque | 310 Nm at 2.800 rpm |
| Engine capacity | 2.231 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 35.3 mpg |
| Consumption extra urban | 53.3 mpg |
| Consumption combined | 44.8 mpg |
| CO2 emission | 167 g/km |
| CO2 label | H |






Internet history

Entry 2





| | |
|---------------|-----------------------------|
| Date | 2022-02-03 |
| Pictures | 29 |
| Listing price | View report |



source: [cargurus.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-02-02 |
| Pictures | 28 |
| Listing price | View report |



source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-02 |
| MOT pass rate | 76 % |
| MOT passed | 13 |
| Failed MOT tests | 4 |
| Total advice items | 54 |
| Total items failed | 7 |

MOT #172024-01-25 14:16

MOT test number482354399429

Result✓ Passed

Next expiry date2025-02-02

- Advice

Coil spring corroded All 4 (5.3.1 (b) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing and worn on the inner edge (5.2.3 (d) (ii))
- Advice

Parking brake has little reserve travel
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2024-01-25 08:41

MOT test number

903553746194

Result**✗ Failed**

- Advice** Parking brake has little reserve travel
- Advice** Coil spring corroded All 4 (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing and worn on the inner edge (5.2.3 (d) (ii))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #15

2023-01-25 08:36

MOT test number

479927496164

Result**✓ Passed**

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Coil spring corroded All 4 (5.3.1 (b) (i))

MOT #14

2023-01-25 08:36

MOT test number

175564477123

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Coil spring corroded All 4 (5.3.1 (b) (i))



| | |
|-----------------|------------------|
| MOT #13 | 2022-02-03 11:04 |
| MOT test number | 514148075928 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #12 | 2020-08-14 16:07 |
| MOT test number | 784357237143 |
| Result | ✓ Passed |



MOT #11

2019-08-16 09:21

MOT test number

898602495915

Result

✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Bumper damaged
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Front Hydraulic brake calliper corroded but not seriously weakened (1.1.16 (d) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Wipers split
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Hydraulic brake calliper corroded but not seriously weakened (1.1.16 (d) (i))

**MOT #10**

2019-08-15 08:44

MOT test number

322869223805

Result**✗ Failed**

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Hydraulic brake calliper corroded but not seriously weakened (1.1.16 (d) (i))
- Advice** Nearside Front Bumper damaged
- Advice** Offside Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Wipers split
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Front Hydraulic brake calliper corroded but not seriously weakened (1.1.16 (d) (i))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #9** 2018-08-07 09:08**MOT test number** 500086452091**Result** ✓ Passed**Advice** Surface rust on n/s/r and o/s/r under body**MOT #8** 2018-08-07 09:08**MOT test number** 415196898991**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Surface rust on n/s/r and o/s/r under body**MOT #7** 2017-07-19 12:09**MOT test number** 745471298753**Result** ✓ Passed**MOT #6** 2016-08-31 13:59**MOT test number** 234178670932**Result** ✓ Passed**MOT #5** 2015-09-28 08:23**MOT test number** 385084637767**Result** ✓ Passed**MOT #4** 2014-09-01 12:55**MOT test number** 196184444232**Result** ✓ Passed**MOT #3** 2013-09-19 12:19**MOT test number** 487552463262**Result** ✓ Passed



| | |
|-----------------|------------------|
| MOT #2 | 2012-09-21 10:20 |
| MOT test number | 528085562252 |
| Result | ✓ Passed |
| MOT #1 | 2010-10-11 10:06 |
| MOT test number | 130034580244 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
2 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 185 |
| MOT expiry date | 2 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | AV57OJU |
| Plate since | 2019-03-29 |
| Current registration | AV57OJU |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 20 |
| First mileage registration | 2007-10-18 |
| Last registration | 2024-01-25 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2007-10-18 | 7 mi |
| Registration #2 | 2010-10-11 | 34.398 mi |
| Registration #3 | 2012-09-21 | 52.191 mi |
| Registration #4 | 2013-09-19 | 60.004 mi |
| Registration #5 | 2014-09-01 | 69.736 mi |
| Registration #6 | 2015-09-28 | 77.678 mi |
| Registration #7 | 2016-08-31 | 85.091 mi |
| Registration #8 | 2017-07-19 | 89.085 mi |
| Registration #9 | 2018-08-07 | 96.196 mi |
| Registration #10 | 2018-08-07 | 96.196 mi |
| Registration #11 | 2019-05-29 | 96.196 mi |
| Registration #12 | 2019-05-29 | 96.196 mi |
| Registration #13 | 2019-05-29 | 96.196 mi |
| Registration #14 | 2019-05-29 | 96.196 mi |
| Registration #15 | 2019-05-29 | 96.196 mi |
| Registration #16 | 2019-05-29 | 96.196 mi |
| Registration #17 | 2019-05-29 | 96.196 mi |
| Registration #18 | 2019-05-29 | 96.196 mi |
| Registration #19 | 2019-05-29 | 96.196 mi |
| Registration #20 | 2019-05-29 | 96.196 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1770 mm |
| Height | 1620 mm |
| Length | 4360 mm |
| Wheel base | 2750 mm |
| Kerb weight | 1495 kg |
| Max. allowed weight | 2160 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |

| | |
|------------------------|------------|
| Number of axles | 2 |
| Engine number | 2AD5279309 |