





report date: 2024-03-28

General information

Make	MAZDA
Model	cx-3 D SPORT NAV
Colour	Blue
Year of manufacture	2016
Top speed	107 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	270 Nm at 2.500 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	60.1 mpg
CO2 emission	123 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-16

Pictures 21

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-09-09
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	14
Total items failed	7

MOT #8	2023-09-08 14:38
MOT test number	813079794828
Result	✓ Passed
Next expiry date	2024-09-09

MOT #7		2022-09-08 12:21
MOT test	number	189039596181
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #6 2022-09-08 09:03 **MOT** test number 643534247620 Result × Failed Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail Offside Rear Rear fog lamp obviously incorrectly positioned (4.5.4 (a)) **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Nearside Rear Tyre tread depth below requirements of 1.6mm 215/50/18 (5.2.3 (e)) Fail **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5

MOT test number

856021708788

Result

✓ Passed

 MOT #4
 2021-09-07 11:39

 MOT test number
 396014371150

 Result
 ★ Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords

MOT #3 2020-07-27 11:27

MOT test number 615913112568

Result \rightarrow Passed

Advice Nearside Front Outer Tyre slightly damaged/cracking or perishing sidewall damage (5.2.3 (d) (ii))

Advice Rear wiper blade split

(5.2.3 (d) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

Result

Advice Offside Front Tyre wearing on edges! Consider replacing.

Advice Front Brake pad(s) wearing thin These pads need replacing! (1.1.13 (a) (ii))

MOT #1

Result

Fail Nearside Rear Tyre has ply or cords exposed Sidewall damage! Part worn tyre! (5.2.3 (d) (ii))

Advice Front Brake pad(s) wearing thin These pads need replacing! (1.1.13 (a) (ii))

Advice Offside Front Tyre wearing on edges! Consider replacing.

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check





Expires: 9 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	9 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MAZDA salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

e when mistery	
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	NK NE
Plate since	
Current registration	alk Mis
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-08-01
Last registration	2023-09-08
Complete history	See info



Registration #1	2016-08-01	19 mi
Registration #2	2019-08-01	43.175 mi
Registration #3	2019-08-02	43.222 mi
Registration #4	2020-07-27	57.947 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	85%
Children	79%
Pedestrian	84%
Safety systems	64%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1535 mm
Length	4275 mm
Wheel base	2570 mm
Kerb weight	1275 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	44
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	S5 30 326532

CarCheck.co.uk page 12/12