



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	COUPE V6
Colour	Red
Year of manufacture	-
Top speed	135 mph
0 - 60 mph	8.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	165 BHP
Max. torque	245 Nm at 4.000 rpm
Cylinders	6
Fuel type	Petrol
Consumption city	19.9 mpg
Consumption extra urban	35.3 mpg
Consumption combined	27.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-17
Pictures	25
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #20	2021-10-11 11:12
MOT test number	576044980559
Result	✓ Passed
Next expiry date	2022-10-10

MOT #19	2021-10-07 16:25
MOT test number	833105819248
Result	✗ Failed
Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))	

MOT #18	2020-12-31 12:33
MOT test number	943417009287
Result	✓ Passed

MOT #17	2020-12-29 16:23
MOT test number	566242381049
Result	✗ Failed
Fail Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))	
Fail Registration plate incorrect (0.1 (c))	
Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail Exhaust has a major leak of exhaust gases at flexi (6.1.2 (a))	
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #16	2019-07-19 10:16
MOT test number	925251582986
Result	✓ Passed

**MOT #15** 2019-07-19 08:48**MOT test number** 169658087635**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))**MOT #14** 2018-07-13 10:41**MOT test number** 210183366071**Result** ✓ Passed**MOT #13** 2017-07-07 09:55**MOT test number** 648449403802**Result** ✓ Passed**MOT #12** 2017-07-07 08:39**MOT test number** 718056485303**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #11** 2016-07-01 13:47**MOT test number** 434382192927**Result** ✓ Passed**MOT #10** 2016-07-01 13:19**MOT test number** 588437033939**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)

**MOT #9** 2015-07-17 09:34**MOT test number** 298768395489**Result** ✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Fuel filler pipe corroded, not leaking
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #8 2014-07-04 09:34**MOT test number** 409375284116**Result** ✓ Passed

- Advice** Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)

MOT #7 2013-07-12 15:12**MOT test number** 445743193174**Result** ✓ Passed**MOT #6** 2013-07-12 14:52**MOT test number** 495463393165**Result** ✗ Failed

- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #5 2012-07-03 09:20**MOT test number** 237065682140**Result** ✓ Passed

**MOT #4** 2012-07-02 15:29**MOT test number** 319624882175**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**MOT #3** 2011-07-18 11:34**MOT test number** 395869391115**Result** ✓ Passed**Advice** Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2010-07-22 10:55**MOT test number** 284833500296**Result** ✓ Passed**MOT #1** 2009-07-21 16:28**MOT test number** 264502909254**Result** ✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-07-31
Last registration	2021-10-11
Complete history	See info



Registration #1	2006-07-31	22 mi
Registration #2	2009-07-21	14.081 mi
Registration #3	2010-07-22	17.867 mi
Registration #4	2011-07-18	21.387 mi
Registration #5	2012-07-02	24.797 mi
Registration #6	2012-07-03	24.797 mi
Registration #7	2013-07-12	28.974 mi
Registration #8	2013-07-12	28.974 mi
Registration #9	2014-07-04	33.253 mi
Registration #10	2015-07-17	37.265 mi
Registration #11	2016-07-01	40.424 mi
Registration #12	2017-07-01	43.583 mi
Registration #13	2018-07-01	46.742 mi
Registration #14	2019-07-01	49.901 mi
Registration #15	2020-07-01	53.060 mi
Registration #16	2021-07-01	56.219 mi
Registration #17	2022-07-01	59.378 mi
Registration #18	2023-07-01	62.537 mi
Registration #19	2024-07-01	65.696 mi
Registration #20	2025-07-01	68.855 mi
Registration #21	2026-07-01	72.014 mi
Registration #22	2027-07-01	75.173 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1335 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G6BA5354638