




report date: 2024-03-29

General information

Make	NISSAN
Model	JUKE TEKNA DIG-T
Colour	White
Year of manufacture	2017
Top speed	111 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	190 Nm at 2.000 rpm
Engine capacity	1.197 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 2

Date	2024-04-05
Pictures	39
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-02-02
Pictures	9
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-04-22
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	42
Total items failed	0

MOT #7	2024-04-23 15:52
MOT test number	457607195824
Result	✓ Passed
Next expiry date	2025-04-22

MOT #6	2024-04-18 11:01
MOT test number	210583155165
Result	✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge and nail in tyre (5.2.3 (e))
- MAJOR** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- MAJOR** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- MAJOR** Rear Exhaust emissions likely to be affected by an exhaust leak joint (8.2.1.1 (b))



MOT #5

2023-09-15 14:53

MOT test number

808163173366

Result

✓ Passed

- Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement beam bushes starting to perish (5.3.4 (a) (i))
- Advice

Offside Rear slightly corroded
- Advice

Offside Front Coil spring corroded slightly (5.3.1 (b) (i))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Suspension arm pin or bush worn but not resulting in excessive movement beam bushes starting to perish (5.3.4 (a) (i))
- Advice

Nearside Rear casing slightly corroded
- Advice

Nearside Front Coil spring corroded slightly (5.3.1 (b) (i))
- Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #4**

2023-09-15 11:05

**MOT test number**

536705801076

**Result****✗ Failed**

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Rear slightly corroded

**Advice** Suspension arm pin or bush worn but not resulting in excessive movement beam bushes starting to perish (5.3.4 (a) (i))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**DANGEROUS** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure large nail in tyre worn inner edge and cracking (5.2.3 (d) (ii))

**Advice** Nearside Front Coil spring corroded slightly (5.3.1 (b) (i))

**Advice** Nearside Rear casing slightly corroded

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement beam bushes starting to perish (5.3.4 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Offside Front Coil spring corroded slightly (5.3.1 (b) (i))

**MOT #3**

2022-09-20 13:36

**MOT test number**

861092544494

**Result**

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement bushes (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement bushes (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #2**

2021-09-08 10:22

**MOT test number**

427674904180

**Result**

✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #1**

2020-09-25 15:52

**MOT test number**

487021128250

**Result**

✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
22 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	22 April 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-09-21
Last registration	2024-04-23
Complete history	<a href="#">See info</a>



Registration #1	2017-09-21	29 mi
Registration #2	2020-09-25	11.779 mi
Registration #3		
Registration #4	2021-09-08	16.097 mi
Registration #5	2022-09-20	25.559 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	81%
Pedestrian	41%
Safety systems	71%
Overall rating	75%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1765 mm
Height	1565 mm
Length	4135 mm
Wheel base	2530 mm
Kerb weight	1307 kg
Max. allowed weight	1710 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

480111A