





### General information

Make	VOLKSWAGEN
Model	TOURAN S TDI BLUEMOTION
Colour	Grey
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg





# Internet history

Entry 1

Date Pictures 2021-07-03

26

Listing price

View report



source: autotrader.co.uk



# MOT history

MOT #14	2021-08-06 10:38
MOT test number	532204238258
Result	✓ Passed
Next expiry date	2022-08-05

MOT #13	2021-08-05 12:01
MOT test number	215504368086
Result	🗙 Failed
Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3	3.4 (b) (i))
Fail Nearside Front Brake hose excessively damaged (1.1.12 (b) (ii))	

MOT #12	2021-02-01 11:08
MOT test number	423389667808
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge worn smooth on inn to limit (5.2.3 (e))	er shoulder and close
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Nearside Rear Tyre obviously under inflated flat (5.2.3 (I))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edg	e (5.2.3 (e))

MOT #11	2020-01-31 13:19
MOT test number	604713086775
Result	✓ Passed

MOT #10	2019-01-02 17:04
MOT test number	750737626609
Result	✓ Passed





МОТ #9		2019-01-02 17:04
MOT test number		462185903525
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))	
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))	

MOT #8	2018-01-25 12:30
MOT test number	687274095451
Result	✓ Passed

MOT #7	2017-01-20 15:36
MOT test number	956947035680
Result	✓ Passed
<b>Advice</b> Nearside Outer Front constant velocity joint gaiter damaged, but pre (2.5.C.1a)	venting the ingress of dirt

МОТ #6	2016-01-23 15:22
MOT test number	575327923153
Result	✓ Passed

MOT #5	2016-01-23 10:38
MOT test number	705610017731
Result	🗙 Failed
<b>Fail</b> Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
<b>Fail</b> Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

МОТ #4	2015-01-06 15:56
MOT test number	495626705082
Result	✓ Passed





MOT #3		2014-01-02 08:41
MOT test numb	ber	846012904035
Result		✓ Passed
Notice Unde	er-trays fitted obscuring some underside components	
Notice Engi	ne covers fitted obscuring some components in the engine bay	
Advice Wind	dscreen has damage to an area less than a 40mm circle outside zone '/	A' (8.3.1d)

101 #2	2013-01-20 09.01
MOT test number	189036523067
Result	✓ Passed

MOT #1	2012-01-21 09:42
MOT test number	628191322026
Result	✓ Passed





### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	Lame
Туре	
Damage 2	AMPLE
Damage 2	E E E E
Date	*
Category	AMP
Туре	

#### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
********	
and the second sec	
***********	
*********	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-02-01
Last registration	2021-08-06
Complete history	See info



Registration #1	2009-02-01	20 mi
Registration #2	2012-01-21	21.008 mi
Registration #3	2013-01-26	29.156 mi
Registration #4	2014-01-02	38.292 mi
Registration #5	2015-01-06	47.749 mi
Registration #6	2016-01-23	58.292 mi
Registration #7	2016-01-23	58.292 mi
Registration #8	2017-01-20	68.364 mi
Registration #9		11.777 esi
Registration #9 Registration #10		10.000 est
-		10.000 est 10.000 est 10.000 est
Registration #10		00.000 est 01.000 est 00.000 est 01.000 est
Registration #10 Registration #11		00.000 est 0.000 est 00.000 est 00.000 est 00.000 est
Registration #10 Registration #11 Registration #12		00,000 est 0,000 est 0,000 est 0,000 est 0,000 est 0,000 est 0,000 est
Registration #10 Registration #11 Registration #12 Registration #13		00.000 460 00.000 460 00.000 460 00.000 460 00.000 460 00.000 460 00.000 460

More info >





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

**NCAP** rating

CarCheck.co.uk

Video

see crash video



#### Dimensions & weight Width 2066 mm Height 1635 mm Length 4407 mm Wheel base 2677 mm Kerb weight 1498 kg Max. allowed weight 2190 kg Additional information **Direct Injection Fuel delivery** Number of doors 5 7 Number of seats

**Engine number** 

BLS0A72002