





report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 SW SPORT
Colour	Black
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	160 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-29

MOT history

MOT #16 2021-10-08 15:02

MOT test number 205392210233

Result \(\sqrt{Passed} \)

Next expiry date 2022-10-12

Advice Coil spring corroded Both rear (5.3.1 (b) (i))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Headlamp has a product on the lens but not seriously reducing light output Both (4.1.4 (b))

MOT #15 2021-10-07 15:09

MOT test number 256631981931

Result X Failed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened strong advise (1.1.14 (a) (ii))

DANGEROUS Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Headlamp has a product on the lens but not seriously reducing light output Both (4.1.4 (b))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Coil spring corroded Both rear (5.3.1 (b) (i))

MOT #14 2020-10-13 11:30

MOT test number 776164176472

Result

Very Passed

MOT #13 2020-10-08 12:41

MOT test number 443119530615

Result X Failed

DANGEROUS Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Offside Rear Exhaust system insecure box bracket brockn (6.1.2 (a))

MAJOR Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

DANGEROUS Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT test number

Result

Advice

Nearside Front Tyre worn close to legal limit/worn on edge very worn (5.2.3 (e))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2019-10-07 09:35 **MOT** test number 941474865358 Result × Failed **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) **MAJOR** Rear Exhaust system insecure (6.1.2 (a)) Advice Nearside Front Tyre worn close to legal limit/worn on edge very worn (5.2.3 (e)) **MAJOR** Central Front Exhaust system insecure (6.1.2 (a)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2018-09-28 14:09
MOT test number	996534427452
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on e	dge (5.2.3 (e))
Advice Offside Front Suspension arm ball joint has slight play	(5.3.4 (a) (i))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #9 2018-09-28 12:22 **MOT** test number 455372183851 Result × Failed **Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) **MAJOR** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i)) **MAJOR** Windscreen washer not working (3.5 (a)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Rear Exhaust system insecure (6.1.2 (a)) MAJOR **MAJOR** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))

MOT #8

MOT test number

Result

Advice Offside front brake fluctuating, but not excessively (3.7.B.3)

Advice Nearside front brake fluctuating, but not excessively (3.7.B.3)

MOT #7 2017-09-28 12:30 **MOT** test number 831164231663 Result × Failed Fail Nearside Front wheel bearing rough when rotated (2.5.A.2) **Advice** Offside front brake fluctuating, but not excessively (3.7.B.3) Fail Offside Front Wheel bolt(s) missing (4.2.A.1e) **Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3) Fail Offside Stop lamp not working (1.2.1b)

CarCheck.co.uk page 4/11



report date: 2024-03-29

MOT #6 2016-10-05 14:02

MOT test number 225336637003

MOT #5 2016-10-05 14:02

MOT test number 903315074790

Result × Failed

Pass with rectification Offside Rear wheel bearing has excessive play (2.6.2)

MOT #4 2015-10-02 09:12

MOT test number 337942149242

Result ✓ Passed

MOT #3 2014-09-20 09:20

MOT test number 318143164443

Result

Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2013-09-27 11:44

MOT test number 309220373429

Result \(\sqrt{Passed} \)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1 2012-09-22 11:16

MOT test number 707576262277

Result \rightarrow Passed

Notice Small cut in n/s/f & n/s/r tyres

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



furthe scinors

RT59BEK

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this PEUGEOT had different number plates.

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-30
Last registration	2021-10-08
Complete history	See info



Registration #1	2009-09-30	15 mi
Registration #2	2012-09-22	30.611 mi
Registration #3	2013-09-27	36.010 mi
Registration #4	2014-09-20	41.350 mi
Registration #5	2015-10-02	48.089 mi
Registration #6	2016-10-05	54.016 mi
Registration #7	2016-10-05	54.016 mi
Registration #8	2017-09-28	62.536 mi
Registration #9	2017-09-28	62.537 mi
Registration #10		11.177 es
Registration #11		11.177 mi
Registration #12		71.777 es
Registration #13		11.177 mi
Registration #14		D 107 au
Registration #15		11.777 es
Registration #15 Registration #16		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1920 mm
Height	1555 mm
Length	4156 mm
Wheel base	2540 mm
Kerb weight	1302 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1:

Number of axles 2

Engine number FHBC0379295