



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Silver
Year of manufacture	2007
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.2 mpg
CO2 emission	203 g/km
CO2 label	K





Internet history

Entry 2

Date	2023-08-25
Pictures	16
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-08-19
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-09-04
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	31
Total items failed	24

MOT #23 2024-04-17 13:55

MOT test number 118111782189

Result ✗ Failed

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #22 2022-09-05 13:39

MOT test number 972563663698

Result ✓ Passed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #21**

2022-09-01 10:44

MOT test number

657289989470

Result**✗ Failed****Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Fail** Rear Registration plate inscription illegible (0.1 (b))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #20**

2021-09-02 15:55

MOT test number

320010984911

Result**✓ Passed****Advice** Rear number plate deteriorated**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2021-08-31 14:38

MOT test number

926674809849

Result**✗ Failed**

- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Bonnet struts not working
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Rear number plate deteriorated
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** 225/45/17
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #18

2020-12-03 10:57

MOT test number

837026969299

Result**✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #17

2019-07-22 15:16

MOT test number

294134483363

Result**✓ Passed**



MOT #16	2018-12-18 16:49
MOT test number	678743345890
Result	✓ Passed
Advice	Bonnet stays defective

MOT #15	2018-12-18 10:19
MOT test number	545710456094
Result	✗ Failed
Fail	Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Advice	Tyre opressures
Fail	Offside Front Position lamp not working (4.2.1 (a))
Advice	Bonnet stays defective

MOT #14	2017-12-15 11:54
MOT test number	601861558165
Result	✓ Passed
Advice	Both front tyres worn on inner and outer edges

MOT #13	2016-12-13 12:18
MOT test number	131668809088
Result	✓ Passed
Advice	Both front tyres worn on inside edge

MOT #12	2016-12-13 09:53
MOT test number	267839900725
Result	✗ Failed
Fail	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Advice	Both front tyres worn on inside edge

**MOT #11** 2016-01-04 12:07**MOT test number** 543653530095**Result** ✓ Passed**MOT #10** 2016-01-04 12:07**MOT test number** 247201168869**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #9** 2015-05-14 13:26**MOT test number** 256164635440**Result** ✓ Passed**MOT #8** 2015-05-08 12:13**MOT test number** 159258925170**Result** ✗ Failed**Fail** Nearside Front Headlamp aim too low (1.8)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**MOT #7** 2014-05-09 15:45**MOT test number** 786869124119**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Front tyres bald on edges**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2014-05-08 09:36**MOT test number** 207018124180**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Front tyres bald on edges**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-05-03 08:31**MOT test number** 716683523195**Result** ✓ Passed**MOT #4** 2013-05-01 18:59**MOT test number** 936921623122**Result** ✗ Failed**Fail** Nearside Rear brake caliper leaking (3.6.A.1)**MOT #3** 2012-07-07 12:38**MOT test number** 509909682169**Result** ✓ Passed**Notice** Damage to nearside rear outer sidewall but not deep enough to reach cords**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Unable to fully test offside rear seatbelt



MOT #2	2011-07-05 15:03
MOT test number	887846081116
Result	✓ Passed
MOT #1	2010-05-29 09:32
MOT test number	441699940169
Result	✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-05-29
Last registration	2024-04-17
Complete history	See info



Registration #1	2007-05-29	14 mi
Registration #2	2010-05-29	18.072 mi
Registration #3	2011-07-05	21.678 mi
Registration #4	2012-07-07	26.128 mi
Registration #5	2013-05-01	26.364 mi
Registration #6	2013-05-03	26.364 mi
Registration #7	2014-05-08	37.902 mi
Registration #8	2014-05-09	37.938 mi
Registration #9	2015-05-08	52.744 mi
Registration #10	2015-05-14	52.928 mi
Registration #11	2016-01-04	54.016 mi
Registration #12	2016-01-04	54.016 mi
Registration #13	2016-12-13	59.850 mi
Registration #14	2016-12-13	59.850 mi
Registration #15	2016-12-13	59.850 mi
Registration #16	2016-12-13	59.850 mi
Registration #17	2016-12-13	59.850 mi
Registration #18	2016-12-13	59.850 mi
Registration #19	2016-12-13	59.850 mi
Registration #20	2016-12-13	59.850 mi
Registration #21	2016-12-13	59.850 mi
Registration #22	2016-12-13	59.850 mi
Registration #23	2016-12-13	59.850 mi
Registration #24	2016-12-13	59.850 mi
Registration #25	2016-12-13	59.850 mi
Registration #26	2016-12-13	59.850 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1342 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC7843532