



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO SL 17 DCI 70
Colour	White
Year of manufacture	2008
Top speed	91 mph
0 - 60 mph	16.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	160 Nm at 1.500 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-13
Pictures	15
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-24
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	22
Total items failed	11

MOT #18	2023-08-23 11:12
MOT test number	293813657033
Result	✓ Passed
Next expiry date	2024-08-24
Advice	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #17	2022-08-25 08:23
MOT test number	209054226390
Result	✓ Passed
Advice	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #16	2021-08-23 10:24
MOT test number	676032271327
Result	✓ Passed

MOT #15	2021-08-17 10:04
MOT test number	936418312214
Result	✗ Failed
Fail	Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Fail	Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
Fail	Nearside Rear Parking (secondary brake) on a single line braking system grabbing severely (1.3.1 (c))

**MOT #14** 2020-07-31 11:55**MOT test number** 928997318466**Result** ✓ Passed**MOT #13** 2019-09-30 10:05**MOT test number** 539990984341**Result** ✓ Passed**MOT #12** 2019-09-30 10:05**MOT test number** 727022381369**Result** ✗ Failed

Pass with rectification Front Brake disc in such a condition that it is seriously weakened Both sides pitted (1.1.14 (a) (ii))

Pass with rectification Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Insecure (6.1.7 (g) (ii))

MOT #11 2018-10-03 10:32**MOT test number** 872161366525**Result** ✓ Passed**MOT #10** 2017-10-07 08:38**MOT test number** 567676447576**Result** ✓ Passed**MOT #9** 2017-10-06 16:06**MOT test number** 874343966752**Result** ✗ Failed

Fail Nearside Front Anti-roll bar linkage insecure (2.4.G.1)

Fail Offside Front Anti-roll bar linkage insecure (2.4.G.1)

**MOT #8** 2016-09-28 07:57**MOT test number** 837430604193**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)
- Advice** Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #7 2015-10-02 09:03**MOT test number** 241767449473**Result** ✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened both fronts (3.5.1i)
- Advice** Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement both fronts (2.4.G.2)

MOT #6 2014-10-08 12:25**MOT test number** 907321784238**Result** ✓ Passed**MOT #5** 2013-12-30 16:48**MOT test number** 757474863344**Result** ✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Nearside front brake slightly binding

**MOT #4** 2013-12-30 09:29**MOT test number** 168724563312**Result** ✗ Failed

- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Notice** Under-trays fitted obscuring some underside components
- Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)
- Notice** Nearside front brake slightly binding
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Notice** Oil leak
- Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2012-12-27 10:26**MOT test number** 745122362390**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components

MOT #2 2011-12-29 12:21**MOT test number** 408513461321**Result** ✓ Passed

- Notice** Front brake pads and brake discs wearing thin



MOT #1	2010-12-30 11:28
MOT test number	160174360336
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✓
MOT

Expires:
24 August 2024

Tax status

Valid until 1 August

Days left

95

MOT expiry date

24 August 2024

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-01-21
Last registration	2023-08-23
Complete history	See info



Registration #1	2008-01-21	24 mi
Registration #2	2010-12-30	51.391 mi
Registration #3	2011-12-29	71.282 mi
Registration #4	2012-12-27	87.776 mi
Registration #5	2013-12-30	97.356 mi
Registration #6	2013-12-30	97.356 mi
Registration #7	2014-10-08	101.784 mi
Registration #8	2015-10-02	106.212 mi
Registration #9	2016-09-28	110.647 mi
Registration #10	2017-10-06	114.840 mi
Registration #11	2018-05-29	121.277 mi
Registration #12	2019-05-29	121.277 mi
Registration #13	2020-05-29	121.277 mi
Registration #14	2021-05-29	121.277 mi
Registration #15	2022-05-29	121.277 mi
Registration #16	2023-05-29	121.277 mi
Registration #17	2024-05-29	121.277 mi
Registration #18	2025-05-29	121.277 mi
Registration #19	2026-05-29	121.277 mi
Registration #20	2027-05-29	121.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2031 mm
Height	1835 mm
Length	4035 mm

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	D242698