




General information

Make	CITROEN
Model	BERLINGO 625 ENTERPRISE L1 HDI
Colour	White
Year of manufacture	2015
Top speed	94 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	185 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	131 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-05-08
MOT pass rate	55 %
MOT passed	6
Failed MOT tests	5
Total advice items	11
Total items failed	11

MOT #11 2023-05-09 15:15

MOT test number 325211032241

Result ✓ Passed

Next expiry date 2024-05-08

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2023-05-09 08:35

MOT test number 826409495821

Result ✗ Failed

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2022-01-22 10:04

MOT test number 297609494455

Result ✓ Passed



MOT #8 2022-01-19 11:58

MOT test number 827846365108

Result ✗ Failed

- Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail Offside Front Tyre tread depth below requirements of 1.6mm worn inner edge recommend tracking checked!! (5.2.3 (e))

MOT #7 2020-12-01 08:15

MOT test number 444136336750

Result ✓ Passed

- Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2019-11-13 13:58

MOT test number 464910533188

Result ✓ Passed

MOT #5 2019-11-13 12:29

MOT test number 246900707005

Result ✗ Failed

- Fail Brake pedal anti-slip provision worn smooth missing (1.1.2 (c))
- Fail Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))



MOT #4	2019-02-01 13:42
MOT test number	478466367478
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3	2019-02-01 10:50
MOT test number	418693621208
Result	✗ Failed
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2	2018-01-31 14:59
MOT test number	800240117922
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2018-01-31 10:11
MOT test number	283353611233
Result	✗ Failed
Fail	Offside Windscreen washer provides insufficient washer liquid (8.2.3)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Central Seat belt locking mechanism does not secure or release (5.2.5a)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
8 May 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	8 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-




Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	LB64DCZ
Plate since	2024-03-28
Current registration	LB64DCZ
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-02-13
Last registration	2023-05-09
Complete history	See info



Registration #1	2015-02-13	19 mi
Registration #2	2018-01-31	22.527 mi
Registration #3	2018-01-31	22.527 mi
Registration #4	2019-02-01	27.016 mi
Registration #5	2019-02-01	27.016 mi
Registration #6	2019-11-13	31.845 mi
Registration #7	2019-11-13	31.845 mi
Registration #8	2019-11-13	31.845 mi
Registration #9	2019-11-13	31.845 mi
Registration #10	2019-11-13	31.845 mi
Registration #11	2019-11-13	31.845 mi
Registration #12	2019-11-13	31.845 mi
Registration #13	2019-11-13	31.845 mi

[More info >](#)



Safety ratings

NCAP rating	★★★★☆	□
Adult	56%	
Children	74%	
Pedestrian	63%	
Safety systems	48%	
Overall rating	59%	
Video	see crash video	

Dimensions & weight

Width	2112 mm
Height	1801 mm
Length	4380 mm
Kerb weight	1304 kg
Max. allowed weight	1945 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBEM3118132