




report date: 2024-03-28

General information

Make	VOLVO
Model	V60 D6 PLUG-IN HYBRID R-DESIGN LUX NAV AWD
Colour	Black
Year of manufacture	2015
Top speed	143 mph
0 - 60 mph	5.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	286 BHP
Max. torque	640 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Electric / Diesel
Consumption combined	156.9 mpg
CO2 emission	48 g/km
CO2 label	A







Internet history

Entry 1

Date	2021-05-22
Pictures	33
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-07-13
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	17
Total items failed	1

MOT #9	2023-07-03 15:08
MOT test number	727436297544
Result	✓ Passed
Next expiry date	2024-07-13
Advice	Small stone chip windscreen \s

MOT #8	2023-07-03 09:40
MOT test number	153108775274
Result	✗ Failed
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Small stone chip windscreen \s
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
DANGEROUS	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #7	2022-06-28 11:54
MOT test number	329655350024
Result	✓ Passed

**MOT #6** 2021-07-14 09:08**MOT test number** 643999602538**Result** ✓ Passed**MOT #5** 2021-02-26 17:15**MOT test number** 273467848852**Result** ✓ Passed

- Advice** Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #4** 2020-03-19 08:58**MOT test number** 595675799091**Result** ✓ Passed

- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Minor** Central Rear Other passenger door catch deteriorated so the door cannot be readily opened or closed (6.2.3 (c) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #3** 2020-03-19 08:58**MOT test number** 958774400895**Result** ✗ Failed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Pass with rectification** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Minor** Central Rear Other passenger door catch deteriorated so the door cannot be readily opened or closed (6.2.3 (c) (i))



MOT #2	2019-03-19 18:35
MOT test number	289177715896
Result	✓ Passed

MOT #1	2017-12-20 09:13
MOT test number	273629310553
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
13 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	13 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	59
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-01-14
Last registration	2023-07-03
Complete history	<a href="#">See info</a>



Registration #1	2015-01-14	25 mi
Registration #2	2017-12-20	28.994 mi
Registration #3	2019-03-19	33.858 mi
Registration #4	2020-03-19	44.438 mi
Registration #5	2020-03-19	44.438 mi
Registration #6	2021-02-26	52.942 mi
Registration #7	2022-05-20	55.277 mi
Registration #8	2022-05-20	55.277 mi
Registration #9	2022-05-20	55.277 mi
Registration #10	2022-05-20	55.277 mi
Registration #11	2023-07-03	55.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	2043 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1550883