





report date: 2024-03-28

## General information

Make	TOYOTA
Model	C-HR DYNAMIC
Colour	Black
Year of manufacture	2018
Top speed	105 mph
0 - 60 mph	11.0 seconds
Gearbox	1 speed CVT

## Engine & fuel consumption

Power	122 BHP
Max. torque	142 Nm at 4.000 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	83.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	74.3 mpg
CO2 emission	87 g/km
CO2 label	Α



CarCheck.co.uk page 1/10



report date: 2024-03-28

## MOT history

MOT expiry date	2024-10-01
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	8
Total items failed	6

MOT #7	2023-10-02 10:51
MOT test number	549315762192
Result	<b>✓</b> Passed
Next expiry date	2024-10-01
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6		2023-10-02 10:51
MOT test number		129225464425
Result		🗙 Failed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Pass with rectification (4.7.1 (b) (ii))  Rear Registration plate lamp inoperative in the case of a single lamp or all lamps		

MOT #5	2023-05-31 17:28
MOT test number	661377853516
Result	✓ Passed
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))	

CarCheck.co.uk page 2/10



report date: 2024-03-28

× Failed

**MOT #4** 2022-06-22 16:04

**MOT test number** 280412509041

Result \rightarrow Passed

Advice Nearside Front

Result

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2022-06-22 12:59

**MOT test number** 299282553777

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Front Windscreen wiper does not clear the windscreen effectively o/s n/s (3.4 (b) (ii))

MOT #2 2021-06-24 14:01

MOT test number 974206548667

Result \( \sqrt{Passed} \)

**MOT #1** 2021-06-22 13:24

MOT test number 632200060258

**Result** X Failed

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

**Fail** Front Windscreen washer provides insufficient washer liquid o/s n/s (3.5 (a))

Minor Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps o/s n/s (4.7.1 (b) (ii))

CarCheck.co.uk page 3/10



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	1 October 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	59
Band	D
First licence fee (12 months)	£ 120,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-

CarCheck.co.uk page 4/10



report date: 2024-03-28

### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

# EF18MWK

report date: 2024-03-28

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u> .	YOTA
***************************************	
***********	
***************************************	
***********	
More in	fo >

# Plate changes

More info >

CarCheck.co.uk page 7/10



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-06-15
Last registration	2023-10-02
Complete history	See info



Registration #1	2018-06-15	17 mi
Registration #2	2021-06-22	14.172 mi
Registration #3	2021-06-24	14.192 mi
Registration #4	2022-06-22	29.154 mi
Registration #5		11.777 esi
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

## Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	95%
Children	77%
Pedestrian	76%
Safety systems	78%
Overall rating	84%
Video	see crash video



# Dimensions & weight

Width	1795 mm
Height	2640 mm
Length	4360 mm
Wheel base	2640 mm
Kerb weight	1420 kg
Max. allowed weight	1860 kg

## Additional information

Fuel tank capacity	43 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 10/1

Number of axles 2

Engine number 2ZRV628029