



RENAULT




report date: 2024-03-28

General information

Make	RENAULT
Model	GRAND SCENIC GRAND DYNAMIQUE TOMTOM DCI FAP
Colour	Black
Year of manufacture	2011
Top speed	112 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	128 g/km
CO2 label	D






Internet history

Entry 1

Date	2022-02-25
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-25
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	38
Total items failed	6

MOT #15 2024-01-26 16:01

MOT test number 672886016842

Result ✓ Passed

Next expiry date 2025-01-25

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14 2023-01-04 14:37

MOT test number 578337734421

Result ✓ Passed

MOT #13 2022-01-18 17:08

MOT test number 739935008051

Result ✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #12** 2021-01-15 11:42**MOT test number** 722489888181**Result** ✓ Passed**MOT #11** 2020-01-13 11:39**MOT test number** 806701657628**Result** ✓ Passed**Advice** Rear indicators faded**Advice** Nearside Front tyre worn on outside edges**MOT #10** 2019-01-08 14:38**MOT test number** 705549008730**Result** ✓ Passed**Advice** Oil leak**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #9** 2019-01-08 14:07**MOT test number** 357451196506**Result** ✗ Failed**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Oil leak**MOT #8** 2018-01-18 16:55**MOT test number** 738551938072**Result** ✓ Passed**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)

**MOT #7** 2018-01-16 15:25**MOT test number** 313893562675**Result** ✗ Failed**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords
205/60 R16 H (4.1.D.1a)**MOT #6** 2017-01-10 17:21**MOT test number** 689067582746**Result** ✓ Passed**MOT #5** 2016-01-16 11:03**MOT test number** 708510457229**Result** ✓ Passed**MOT #4** 2015-01-08 13:53**MOT test number** 486098405080**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2015-01-07 11:03
MOT test number	255317905087
Result	✗ Failed
Fail	Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)
Notice	Offside front tyre on 3mm and wearing on inner edge
Fail	Nearside Rear Brake hose excessively chafed (3.6.B.4d)
Advice	Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Under-trays fitted obscuring some underside components

MOT #2	2014-01-20 11:18
MOT test number	849720624091
Result	✓ Passed
Notice	Service indicator on
Notice	Nearside rear tyre is winter fitment, has uneven wear to inside shoulder and is worn to legal limit
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Vehicle's internal headlight adjuster altered to recheck lights
Notice	Clutch pedal anti-slip pad missing
Notice	Temp repair made to nearside side repeater lamp (MOT requirements met at time of test)
Notice	Nearside door mirror damaged (no sharp edges) (MOT requirements met at time of test)
Notice	Items removed from driver's view prior to test



MOT #1

2014-01-19 15:01

MOT test number

427599114048

Result		✗ Failed
Notice	Vehicle's internal headlight adjuster altered to recheck lights	
Notice	Clutch pedal anti-slip pad missing	
Fail	Nearside Side repeater insecure (1.4.A.2b)	
Notice	Nearside rear tyre is winter fitment, has uneven wear to inside shoulder and is worn to legal limit	
Notice	Nearside door mirror damaged (no sharp edges) (MOT requirements met at time of test)	
Notice	Items removed from driver's view prior to test	
Notice	Service indicator on	
Notice	Offside rear tyre has 3x 'nail' in tread	
Fail	Offside Front Road wheel bead rim badly distorted (4.2.A.1a)	
Notice	Child seat fitted not allowing full inspection of adult belt	



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-01-10
Last registration	2024-01-26
Complete history	See info



Registration #1	2011-01-10	10 mi
Registration #2	2014-01-19	33.612 mi
Registration #3	2014-01-20	33.625 mi
Registration #4	2015-01-07	43.021 mi
Registration #5	2015-01-08	43.077 mi
Registration #6	2016-01-16	56.694 mi
Registration #7	2017-01-10	66.238 mi
Registration #8	2018-01-16	73.444 mi
Registration #9	2018-01-18	73.471 mi
Registration #10	2019-01-20	75.277 mi
Registration #11	2019-01-20	75.277 mi
Registration #12	2019-01-20	75.277 mi
Registration #13	2019-01-20	75.277 mi
Registration #14	2019-01-20	75.277 mi
Registration #15	2019-01-20	75.277 mi
Registration #16	2019-01-20	75.277 mi
Registration #17	2019-01-20	75.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	76%
Pedestrian	42%
Safety systems	99%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1845 mm
Height	1672 mm
Length	4573 mm
Wheel base	2770 mm
Kerb weight	1430 kg
Max. allowed weight	2128 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number	D172973
---------------	---------