



report date: 2024-03-29

General information

Make	FIAT
Model	GRAND PUNTO ACTIVE
Colour	Red
Year of manufacture	2008
Top speed	96 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E






## Internet history

### Entry 4


Date	2022-05-12
Pictures	44
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 3

Date	2021-07-31
Pictures	15
Listing price	<a href="#">View report</a>



source: [yesauto.com](https://www.yesauto.com)

### Entry 2

Date	2021-07-15
Pictures	0
Listing price	<a href="#">View report</a>

source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 1

Date	2021-07-14
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-14
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	46
Total items failed	10

MOT #20	2023-07-14 10:49
MOT test number	651925811226
Result	✓ Passed
Next expiry date	2024-07-14
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19** 2023-07-14 10:49**MOT test number** 424865576333**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #18** 2022-07-11 10:43**MOT test number** 307319744660**Result** ✓ Passed**MOT #17** 2022-07-08 14:59**MOT test number** 523394946920**Result** ✗ Failed**MAJOR** Oil leaking excessively from engine (8.4.1 (a) (i))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MOT #16** 2021-07-15 13:47**MOT test number** 799308016670**Result** ✓ Passed

**MOT #15**

2020-09-07 09:30

**MOT test number**

286852036572

**Result**

✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive sump corroded (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear exhaust silencer deteriorated

**MOT #14**

2019-09-11 13:39

**MOT test number**

477500102198

**Result**

✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Items removed from driver's view prior to test
- Advice** Winter tyre fitted to nearside rear wheel
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edges (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear exhaust silencer deteriorated

**MOT #13**

2019-09-11 13:39

**MOT test number**

800610439153

**Result****✗ Failed****Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Winter tyre fitted to nearside rear wheel**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Items removed from driver's view prior to test**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear exhaust silencer deteriorated**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edges (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12**

2018-09-21 13:59

**MOT test number**

950671010711

**Result****✓ Passed****MOT #11**

2018-09-14 12:39

**MOT test number**

106962339546

**Result****✗ Failed****MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MAJOR** Nearside Rear Position lamp not working (4.2.1 (a))

**MOT #10** 2017-09-05 17:53**MOT test number** 547962082926**Result** ✓ Passed**MOT #9** 2017-09-02 14:19**MOT test number** 810211254965**Result** ✗ Failed**Advice** Offside Front Outer Tyre worn close to the legal limit edge (4.1.E.1)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Nearside Front Outer Tyre worn close to the legal limit edge (4.1.E.1)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Advice** Offside Rear Outer Nail in tyre edge of tyre not repairable**MOT #8** 2016-09-06 13:40**MOT test number** 891803876411**Result** ✓ Passed**MOT #7** 2016-08-31 08:54**MOT test number** 560073044340**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #6** 2015-11-28 10:50**MOT test number** 888488413132**Result** ✓ Passed





MOT #5	2014-11-15 13:54
MOT test number	648989814315
Result	✓ Passed
MOT #4	2013-11-23 14:53
MOT test number	659657723312
Result	✓ Passed
MOT #3	2012-11-17 15:43
MOT test number	82670222373
Result	✓ Passed
MOT #2	2011-11-16 15:44
MOT test number	998400421360
Result	✓ Passed
MOT #1	2011-11-16 15:44
MOT test number	446380021477
Result	✗ Failed
<div>Pass with rectification</div> Nearside Stop lamp not working (1.2.1b)	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
14 July 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	14 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2008-11-27
Last registration	2023-07-14
Complete history	<a href="#">See info</a>



Registration #1	2008-11-27	14 mi
Registration #2	2011-11-16	17.503 mi
Registration #3	2012-11-17	22.264 mi
Registration #4	2013-11-23	25.891 mi
Registration #5	2014-11-15	30.042 mi
Registration #6	2015-11-28	34.816 mi
Registration #7	2016-08-31	38.387 mi
Registration #8	2016-09-06	38.387 mi
Registration #9	2017-09-02	46.570 mi
Registration #10	2017-09-05	46.609 mi
Registration #11	2018-09-14	52.041 mi
Registration #12	2018-09-21	52.045 mi
Registration #13	2019-09-02	52.045 mi
Registration #14	2019-09-02	52.045 mi
Registration #15	2019-09-02	52.045 mi
Registration #16	2019-09-02	52.045 mi
Registration #17	2019-09-02	52.045 mi
Registration #18	2019-09-02	52.045 mi
Registration #19	2019-09-02	52.045 mi
Registration #20	2019-09-02	52.045 mi
Registration #21	2019-09-02	52.045 mi
Registration #22	2019-09-02	52.045 mi
Registration #23	2019-09-02	52.045 mi
Registration #24	2019-09-02	52.045 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	4363732