



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 T3 SE
Colour	White
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-08
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-22
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #11	2023-08-23 10:33
MOT test number	895562361858
Result	✓ Passed
Next expiry date	2024-08-22
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened worn (1.1.14 (a) (ii))
Advice	Nearside Front Inner Tyre slightly damaged/cracking or perishing wall (5.2.3 (d) (ii))

MOT #10	2022-02-24 12:18
MOT test number	968501093494
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9	2021-02-20 12:35
MOT test number	995313595692
Result	✓ Passed
Minor	Windscreen wiper blade defective Both front (3.4 (b) (i))

MOT #8	2020-02-05 17:59
MOT test number	192821361430
Result	✓ Passed

**MOT #7** 2019-02-28 17:51**MOT test number** 445313683445**Result** ✓ Passed**MOT #6** 2018-02-12 15:19**MOT test number** 107573800430**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2017-02-18 16:51**MOT test number** 810858761709**Result** ✓ Passed**MOT #4** 2016-02-20 11:27**MOT test number** 143256442430**Result** ✓ Passed**MOT #3** 2015-02-02 13:52**MOT test number** 279783135098**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test**MOT #2** 2014-01-31 16:08**MOT test number** 288891334059**Result** ✓ Passed



MOT #1	2014-01-31 16:08
MOT test number	466041534032
Result	✗ Failed
Pass with rectification	Centre Stop lamp not working (1.2.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
22 August 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	22 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-02-21
Last registration	2023-08-23
Complete history	See info



Registration #1	2011-02-21	23 mi
Registration #2	2014-01-31	17.858 mi
Registration #3	2015-02-02	29.868 mi
Registration #4	2016-02-20	39.035 mi
Registration #5	2017-02-18	46.498 mi
Registration #6	2018-02-12	53.762 mi
Registration #7	2019-02-09	61.026 mi
Registration #8	2020-02-05	68.290 mi
Registration #9	2021-02-02	75.554 mi
Registration #10	2022-01-28	82.818 mi
Registration #11	2023-01-24	90.082 mi
Registration #12	2023-08-23	97.346 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1885 mm
Height	1484 mm
Length	4028 mm
Wheel base	2775 mm
Kerb weight	1513 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	1061763
---------------	---------