



report date: 2024-03-28

General information

| | |
|---------------------|-----------------|
| Make | CITROEN |
| Model | DS3 DSPORT PLUS |
| Colour | White |
| Year of manufacture | 2014 |
| Top speed | 132 mph |
| 0 - 60 mph | 8.2 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 155 BHP |
| Max. torque | 240 Nm at 1.750 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 35.3 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 47.9 mpg |
| CO2 emission | 137 g/km |
| CO2 label | E |







Internet history

Entry 2


| | |
|---------------|-----------------------------|
| Date | 2022-12-17 |
| Pictures | 14 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-17 |
| Pictures | 42 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-01-24 |
| MOT pass rate | 57 % |
| MOT passed | 8 |
| Failed MOT tests | 6 |
| Total advice items | 17 |
| Total items failed | 17 |

MOT #14 2024-01-25 13:10

MOT test number 250935660738

Result ✓ Passed

Next expiry date 2025-01-24

- Advice** Nearside Front bumper damaged - no sharp edges at time of test
- Advice** Vehicle underside has general age related corrosion front to rear
- Advice** Nearside Front inner wheel arch loose - catching on wheel when on full lock

MOT #13 2024-01-17 12:35

MOT test number 460682186584

Result ✗ Failed

- Fail** Windscreen washer not working (3.5 (a))
- Advice** Nearside Front inner wheel arch loose - catching on wheel when on full lock
- Fail** Nearside Reversing lamp inoperative (4.6.1 (a))
- Advice** Nearside Front bumper damaged - no sharp edges at time of test
- Advice** Vehicle underside has general age related corrosion front to rear
- Fail** Nearside Front Tyre has ply or cords exposed inner wall, tyre inner edge also worn, tread level down to 1.6mm, tyre outer wall also perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #12** 2023-01-19 09:09**MOT test number** 614213332982**Result** ✓ Passed**MOT #11** 2022-05-18 14:31**MOT test number** 873190014432**Result** ✓ Passed**MOT #10** 2022-05-17 08:42**MOT test number** 507003848678**Result** ✗ Failed

- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Reversing lamp inoperative (4.6.1 (a))
- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #9 2021-05-15 10:54**MOT test number** 137111538408**Result** ✓ Passed

- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #8 2021-05-15 10:53**MOT test number** 418708426534**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #7** 2020-05-19 10:51**MOT test number** 395596998935**Result** ✓ Passed**MOT #6** 2020-05-19 08:38**MOT test number** 640011028556**Result** ✗ Failed

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #5 2019-04-12 07:46**MOT test number** 344337588128**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear position light slight damage

MOT #4 2019-04-11 09:56**MOT test number** 629275187627**Result** ✗ Failed

- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure inner and outer sidewalls (5.2.3 (d) (ii))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear position light slight damage
- Fail** Reversing lamp inoperative (4.6.1 (a))

**MOT #3** 2018-04-17 06:49**MOT test number** 560173345970**Result** ✓ Passed

Advice Nearside Rear Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)

MOT #2 2017-06-07 10:50**MOT test number** 298905443703**Result** ✓ Passed

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1 2017-06-06 16:14**MOT test number** 998347388487**Result** ✗ Failed

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
24 January 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 63 |
| MOT expiry date | 24 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 0 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2014-06-30 |
| Last registration | 2024-01-25 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2014-06-30 | 13 mi |
| Registration #2 | 2017-06-06 | 27.988 mi |
| Registration #3 | 2017-06-07 | 27.988 mi |
| Registration #4 | 2018-04-17 | 34.753 mi |
| Registration #5 | 2019-04-11 | 43.843 mi |
| Registration #6 | 2019-04-12 | 43.844 mi |
| Registration #7 | 2020-05-19 | 53.393 mi |
| Registration #8 | 2020-05-19 | 53.393 mi |
| Registration #9 | 2021-05-15 | 57.770 mi |
| Registration #10 | 2022-05-20 | 59.277 mi |
| Registration #11 | 2022-05-20 | 59.277 mi |
| Registration #12 | 2022-05-20 | 59.277 mi |
| Registration #13 | 2022-05-20 | 59.277 mi |
| Registration #14 | 2022-05-20 | 59.277 mi |
| Registration #15 | 2022-05-20 | 59.277 mi |
| Registration #16 | 2022-05-20 | 59.277 mi |
| Registration #17 | 2022-05-20 | 59.277 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 87% |
| Children | 71% |
| Pedestrian | 35% |
| Safety systems | 83% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1715 mm |
| Height | 1483 mm |
| Length | 3948 mm |
| Wheel base | 2464 mm |
| Kerb weight | 1090 kg |
| Max. allowed weight | 1619 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 48 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | FJBS1994527 |