






report date: 2024-03-29

#### General information

| Make                | RENAULT                    |
|---------------------|----------------------------|
| Model               | TRAFIC SL27DCI 100 SWB P/V |
| Colour              | Silver                     |
| Year of manufacture | 2005                       |
| Top speed           | 97 mph                     |
| Gearbox             | 6 speed Manual             |

# Engine & fuel consumption

| Power                   | 100 BHP             |
|-------------------------|---------------------|
| Max. torque             | 240 Nm at 2.000 rpm |
| Engine capacity         | 1.870 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 31.7 mpg            |
| Consumption extra urban | 43.5 mpg            |
| Consumption combined    | 38.2 mpg            |



CarCheck.co.uk page 1/12



2022-02-01 08:22

MOT history

MOT #18

| MOT expiry date    | 2025-01-31 |
|--------------------|------------|
| MOT pass rate      | 71 %       |
| MOT passed         | 15         |
| Failed MOT tests   | 6          |
| Total advice items | 29         |
| Total items failed | 10         |

| MOT #21          | 2024-01-31 07:27 |
|------------------|------------------|
| MOT test number  | 301502566743     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-01-31       |

| MOT #20         | 2023-02-01 11:48 |
|-----------------|------------------|
| MOT test number | 629430721282     |
| Result          | ✓ Passed         |

| MOT #19         | 2022-02-01 08:22 |
|-----------------|------------------|
| MOT test number | 575913287397     |
| Result          | ✓ Passed         |

| MOT test number         |  | 308806931781    |
|-------------------------|--|-----------------|
| Result                  |  | <b>★</b> Failed |
| Pass with rectification | Nearside Front Road wheel fixing missing (5.2.1 (a) (i)) |                 |

CarCheck.co.uk page 2/12



**MOT #17** 2021-02-01 11:46

MOT test number 138362033467

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Offside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #16** 2021-01-29 14:47

MOT test number 901797545786

Result X Failed

Advice Offside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))

MAJOR Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #15 2019-10-30 15:51

MOT test number 511785528945

Result 

Passed

**MOT #14** 2018-07-12 11:29

MOT test number 715425967286

**Advice** Windscreen has a small crack

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

CarCheck.co.uk page 3/12



MOT #13 2018-07-12 11:29

**MOT test number** 651168324527

**Result** X Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Windscreen has a small crack

**MOT #12** 2017-06-16 12:26

**MOT test number** 490534524138

**Advice** Offside Front tyre worn on inner tread

**Advice** Front Play in steering rack inner joint(s)

**MOT #11** 2016-06-07 15:02

MOT test number 936335309117

Result \( \sqrt{Passed} \)

**MOT #10** 2015-05-29 15:54

MOT test number 835369845195

**Result** 
✓ Passed

MOT #9 2015-05-28 09:35

MOT test number 368888945144

Result × Failed

Pass with rectification Offside Headlamp not working on dipped beam (1.7.5a)

**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

**Fail** Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 4/12



Result

GY55KMJ report date: 2024-03-29

**X** Failed

MOT #8 2014-01-21 15:26

**MOT test number** 395921324075

Result \square Passed

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**Notice** Play in steering rack inner joint(s)

**MOT #7** 2014-01-14 17:02

MOT test number 355494014052

**Fail** Offside Front Headlamp aim too high (1.8)

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**Notice** Play in steering rack inner joint(s)

Fail Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

Fail Nearside Front Headlamp aim too low (1.8)

MOT #6 2013-02-09 08:47

MOT test number 957550443095

**Notice** Nail in o/s/r tyre (looks unrepairable)

**Notice** O/s/f steering rack gaitor damp

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Notice** Play in steering rack inner joint(s)

CarCheck.co.uk page 5/12



MOT #5

MOT test number

Fesult

Advice Offside Track rod end ball joint has slight play (2.2.B.1f)

Notice Items removed from driver's view prior to test

MOT #4 2010-11-09 16:41 **MOT** test number 340393510387 Result ✓ Passed **MOT** #3 2010-11-08 15:45 **MOT test number** 473982110409 Result × Failed Nearside Front Track rod end ball joint has excessive play (2.2.B.1f) Fail Fail Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

MOT #2

MOT test number

650748109361

Result

Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f)

Notice Nail in nearside rear tyre

MOT test number

Result

Notice Unable to fully inspect front brake pads

Advice Offside Track rod end ball joint has slight play (2.2.B.1f)

CarCheck.co.uk page 6/12



#### Tax & MOT check



Tax status

Days left

MOT expiry date

See MOT history

Valid until 1 January

246

MOT expiry date

31 January 2025

Full MOT history

CarCheck.co.uk page 7/12



#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



## Owner history

| For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.   |             |
|--|-------------|
|  |             |
|  |             |
|  |             |
|  |             |
| THE STATE OF THE S |             |
|  |             |
| ***************************************  |             |
|  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this RENAULT had different number plates.   |             |
| Number of sisters  |             |
| access of passing  |             |
| Current registration   | NK NK       |
| Plate since  |             |
| Current registration   | UK UK       |
| Plate since  |             |
|  | More info > |

CarCheck.co.uk page 9/12



#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 


More info >

CarCheck.co.uk page 10/12



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 22         |
| First mileage registration | 2005-09-30 |
| Last registration          | 2024-01-31 |
| Complete history           | See info   |



| Registration #1  | 2005-09-30 | 7 mi       |
|------------------|------------|------------|
| Registration #2  | 2008-10-16 | 61.109 mi  |
| Registration #3  | 2009-11-04 | 66.272 mi  |
| Registration #4  | 2010-11-08 | 73.620 mi  |
| Registration #5  | 2010-11-09 | 73.690 mi  |
| Registration #6  | 2012-02-10 | 83.608 mi  |
| Registration #7  | 2013-02-09 | 90.429 mi  |
| Registration #8  | 2014-01-14 | 96.429 mi  |
| Registration #9  | 2014-01-21 | 96.429 mi  |
| Registration #10 | 2015-05-28 | 120.278 mi |
| Registration #11 | 2015-05-29 | 120.278 mi |
| Registration #12 |            | 11.777 es  |
| Registration #13 |            | 9.777 es   |
| Registration #14 |            | 11.777 es  |
| Registration #15 |            | 9.777 es   |
| Registration #16 |            | 11.777 es  |
| Registration #17 |            | 11.777 es  |
| Registration #18 |            | 11.777 es  |
| Registration #19 |            | 11.777 es  |
| Registration #20 |            | 11.777 es  |
| Registration #21 |            | 11.777 es  |
| Registration #22 |            | 11.777 es  |
|                  |            |            |

More info >

CarCheck.co.uk page 11/12



## Car features

| S0225 | Air conditioning |
|-------|------------------|
| 50295 |                  |
| 60482 |                  |
| 60501 |                  |
| 60566 |                  |
| 60567 |                  |
| 50569 |                  |

# Dimensions & weight

| Width       | 2232 mm |
|-------------|---------|
| Length      | 4782 mm |
| Kerb weight | 1677 kg |

# Additional information

| Fuel tank capacity | 90 I             |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of doors    | 4                |
| Number of seats    | 3                |
| Engine number      | C414332          |

CarCheck.co.uk page 12/12