



report date: 2024-03-28

General information

Make	VOLVO
Model	V90 D4 R-DESIGN
Colour	Black
Year of manufacture	2019
Top speed	127 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	47.9 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-10-09
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-23
MOT pass rate	67 %
MOT passed	2
Failed MOT tests	1
Total advice items	18
Total items failed	0

MOT #3	2024-02-29 17:21
MOT test number	317056549811
Result	✓ Passed
Next expiry date	2025-03-23
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	ENGINE COVER & UNDER TRAYS & OUTER SILL COVERS FITTED

**MOT #2** 2024-02-29 11:32**MOT test number** 775231208322**Result** ✗ Failed**MAJOR** Nearside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**MAJOR** Nearside Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** ENGINE COVER & UNDER TRAYS & OUTER SILL COVERS FITTED**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MAJOR** Front Windscreen washer not working (3.5 (a))**MAJOR** Offside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**MAJOR** Offside Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #1** 2023-03-24 09:36**MOT test number** 383646634269**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge WORN ON INNER EDGE & CLOSE TO LIMIT (5.2.3 (e))**Advice** ENGINE COVER & UNDER TRAYS & OUTER SILL COVERS FITTED**Advice** Offside Front Tyre worn close to legal limit/worn on edge WORN ON INNER EDGE & CLOSE TO LIMIT (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
23 March 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	23 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>First licence fee (12 months)</b>	£ 210,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 255,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2019-06-28
Last registration	2024-02-29
Complete history	<a href="#">See info</a>



Registration #1	2019-06-28	11 mi
Registration #2		
Registration #3	2023-03-24	37.357 mi
Registration #4		
Registration #5		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1999 mm
Height	1658 mm
Length	4688 mm
Max. allowed weight	2390 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	3179210