



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Black
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 2



Date	2022-02-22
Pictures	50
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-09-05
Pictures	26
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-02-27
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	17
Total items failed	3

MOT #13	2024-02-10 12:47
MOT test number	527996717243
Result	✓ Passed
Next expiry date	2025-02-27

MOT #12	2024-02-10 12:47
MOT test number	852301687808
Result	✗ Failed
<b>Pass with rectification</b> Registration plate insecure both (0.1 (a))	

MOT #11	2023-02-28 14:45
MOT test number	667024136825
Result	✓ Passed

MOT #10	2023-02-28 12:59
MOT test number	933557919218
Result	✗ Failed
<b>MAJOR</b> Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))	
<b>DANGEROUS</b> Nearside Front Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))	
<b>MAJOR</b> Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))	
<b>DANGEROUS</b> Offside Front Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))	

**MOT #9** 2022-02-28 16:50**MOT test number** 240306037773**Result** ✓ Passed**MOT #8** 2020-12-07 14:10**MOT test number** 974760108143**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge scrubbed on inside edge (5.2.3 (e))**MOT #7** 2020-12-07 09:56**MOT test number** 838864653157**Result** ✗ Failed**MAJOR** Nearside Front Service brake excessively binding (1.2.1 (f))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge scrubbed on inside edge (5.2.3 (e))**MOT #6** 2019-06-20 11:22**MOT test number** 287308975874**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2019-06-20 09:23**MOT test number** 880007591981**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #4** 2018-06-18 14:00**MOT test number** 774309845441**Result** ✓ Passed**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #3** 2017-06-05 13:48**MOT test number** 392950857149**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2017-05-27 08:42**MOT test number** 297739189753**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #1** 2016-06-16 14:30**MOT test number** 164170958968**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
27 February 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	27 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-06-18
Last registration	2024-02-10
Complete history	<a href="#">See info</a>



Registration #1	2013-06-18	18 mi
Registration #2	2016-06-16	74.891 mi
Registration #3	2017-05-27	94.851 mi
Registration #4	2017-06-05	95.178 mi
Registration #5	2018-06-18	108.376 mi
Registration #6	2019-06-20	122.653 mi
Registration #7	2019-06-20	122.653 mi
Registration #8	2020-12-07	133.126 mi
Registration #9	2020-12-07	133.126 mi
Registration #10	2020-12-07	133.126 mi
Registration #11	2020-12-07	133.126 mi
Registration #12	2020-12-07	133.126 mi
Registration #13	2020-12-07	133.126 mi
Registration #14	2020-12-07	133.126 mi
Registration #15	2020-12-07	133.126 mi
Registration #16	2020-12-07	133.126 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1880 mm
Height	1690 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	1963 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	D4HBCU679580