



report date: 2024-03-28

General information

Make	FIAT
Model	GRAND PUNTO ACTIVE
Colour	Grey
Year of manufacture	2008
Top speed	96 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-08-29
Pictures	22
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-08-28
Pictures	22
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-15
MOT pass rate	52 %
MOT passed	11
Failed MOT tests	10
Total advice items	63
Total items failed	9

MOT #21	2023-08-16 15:08
MOT test number	877659098685
Result	✓ Passed
Next expiry date	2024-08-15
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #20	2023-08-03 11:08
MOT test number	448252998742
Result	✗ Failed
MAJOR	Battery insecure and likely to fall from carrier (4.13 (a) (ii))
Advice	Rear Coil spring corroded (5.3.1 (b) (i))
MAJOR	Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))
MAJOR	Rear Brakes imbalanced across an axle (1.2.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Offside Rear Service brake excessively binding (1.2.1 (f))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
MAJOR	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
MAJOR	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
DANGEROUS	Front Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))

**MOT #19**

2023-06-23 13:02

MOT test number

232473877076

Result**✗ Failed**

- MAJOR** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))
- MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- DANGEROUS** Front Brakes imbalanced across an axle by more than 50% Axle 1 (1.2.1 (b) (ii))
- MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))
- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #18

2021-08-23 15:07

MOT test number

563970841825

Result**✓ Passed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
- Advice** Rear Brake hose has slight corrosion to ferrule Both (1.1.12 (f) (i))
- Advice** Rear axle corroded
- Advice** Rear Shock absorbers has slight external damage to the casing Both (corroded) (5.3.2 (b))

**MOT #17**

2021-08-16 11:34

MOT test number

601532837348

Result**✗ Failed**

- Advice** Rear Brake hose has slight corrosion to ferrule Both (1.1.12 (f) (i))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Rear axle corroded
- MAJOR** Front Sub-frame corroded and seriously weakened Nearside & Offside (5.3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
- Advice** Rear Shock absorbers has slight external damage to the casing Both (corroded) (5.3.2 (b))
- MAJOR** Nearside Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #16

2020-08-26 15:40

MOT test number

817195632691

Result**✓ Passed**

- Advice** Oil leak, but not excessive sump porous (8.4.1 (a) (i))
- Advice** Coolant leak radiator

MOT #15

2020-08-26 11:21

MOT test number

464832461105

Result**✗ Failed**

- Advice** Coolant leak radiator
- MAJOR** Exhaust has a major leak of exhaust gases Front pipe to centre flange and flexi (6.1.2 (a))
- Advice** Oil leak, but not excessive sump porous (8.4.1 (a) (i))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**MOT #14** 2019-08-30 16:15**MOT test number** 489915610564**Result** ✓ Passed**MOT #13** 2019-08-30 08:17**MOT test number** 580127578227**Result** ✗ Failed

MAJOR Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Oil leak, but not excessive engine oil filter area (8.4.1 (a) (i))

MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #12 2018-08-30 14:18**MOT test number** 589931519400**Result** ✓ Passed

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Front Tyre worn close to legal limit/worn on edge both front wearing on inner edge (5.2.3 (e))

MOT #11 2017-08-29 08:59**MOT test number** 594423763696**Result** ✓ Passed

Advice Both front tyres feathered inside edges

Advice Offside Front Front wheel bearing has slight play (2.5.A.3c)

Advice Rear Exhaust noisy tailbox baffles going (7.1.4)

Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Rear Exhaust has a minor leak of exhaust gases tailbox joint (7.1.2)

**MOT #10** 2017-08-28 14:19**MOT test number** 281825503451**Result** ✗ Failed**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Rear Exhaust noisy tailbox baffles going (7.1.4)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Both front tyres feathered inside edges**Advice** Rear Exhaust has a minor leak of exhaust gases tailbox joint (7.1.2)**Fail** Rear parking (secondary) brakes imbalanced n/s slow (3.7.B.6b)**MOT #9** 2016-08-16 13:33**MOT test number** 798683563281**Result** ✓ Passed**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**MOT #8** 2016-08-16 10:26**MOT test number** 182340071170**Result** ✗ Failed**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #7** 2015-08-19 11:20**MOT test number** 697391335233**Result** ✓ Passed

**MOT #6**

2014-09-01 16:24

MOT test number

955974544264

Result

✓ Passed

Notice Exhaust very corroded.**Notice** N/s & o/s rear tyre perished.**MOT #5**

2014-08-25 15:04

MOT test number

919957534260

Result

✗ Failed

Fail Offside rear parking brake recording little or no effort (3.7.B.6a)**Notice** Exhaust very corroded.**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** N/s & o/s rear tyre perished.**MOT #4**

2013-09-03 15:33

MOT test number

609746643267

Result

✓ Passed

MOT #3

2013-08-30 15:39

MOT test number

659692943267

Result

✗ Failed

Fail Offside Front front brake binding (3.7.B.1)**Fail** Rear parking (secondary) brakes imbalanced (3.7.B.6b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #2

2011-09-28 15:22

MOT test number

649941971211

Result

✓ Passed

Advice

Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Notice

Advise both front tyres on 3 mm

MOT #1

2011-09-28 15:22

MOT test number

366871071487

Result

✗ Failed

Pass with rectification

Bonnet retaining device ineffective (8.4.2)

Advice

Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Notice

Advise both front tyres on 3 mm



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
15 August 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-09-29
Last registration	2023-08-16
Complete history	See info



Registration #1	2008-09-29	26 mi
Registration #2	2011-09-28	25.604 mi
Registration #3	2013-08-30	28.728 mi
Registration #4	2013-09-03	28.728 mi
Registration #5	2014-08-25	34.337 mi
Registration #6	2014-09-01	34.480 mi
Registration #7	2015-08-19	40.064 mi
Registration #8	2016-08-16	43.547 mi
Registration #9	2016-08-16	43.547 mi
Registration #10	2017-08-28	47.510 mi
Registration #11	2017-08-29	47.510 mi
Registration #12	2018-08-30	49.797 mi
Registration #13	2019-08-30	51.077 mi
Registration #14	2019-08-30	51.077 mi
Registration #15	2019-08-30	51.077 mi
Registration #16	2019-08-30	51.077 mi
Registration #17	2019-08-30	51.077 mi
Registration #18	2019-08-30	51.077 mi
Registration #19	2019-08-30	51.077 mi
Registration #20	2019-08-30	51.077 mi
Registration #21	2019-08-30	51.077 mi
Registration #22	2019-08-30	51.077 mi
Registration #23	2019-08-30	51.077 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4363732