



ND57SZG

report date: 2024-03-28

General information

Make	SUZUKI
Model	JIMNY JLX PLUS
Colour	Blue
Year of manufacture	2007
Top speed	87 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	110 Nm at 4.100 rpm
Engine capacity	1.328 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-02-04
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-08-08
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	34
Total items failed	14

MOT #19 2023-08-09 12:54

MOT test number 631595396243

Result ✓ Passed

Next expiry date 2024-08-08

- Advice** Fresh under seal
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))

MOT #18 2022-12-13 14:14

MOT test number 902691759992

Result ✓ Passed

- Minor** Front Headlamp lens slightly defective o/s and n/s (4.1.1 (b) (i))
- Advice** Nearside Front Nail in tyre and perished
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Chassis and suspension corroded (all)
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened o/s and n/s (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #17**

2022-12-06 09:24

MOT test number

517867897107

Result**✗ Failed**

- Advice** Chassis and suspension corroded (all)
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Axle king pin is loose in the axle beam (5.1.2 (d) (i))
- Minor** Front Headlamp lens slightly defective o/s and n/s (4.1.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened o/s and n/s (1.1.14 (a) (ii))
- Fail** Position lamp not working all lamps (4.2.1 (a) (ii))
- Advice** Nearside Front Nail in tyre and perished
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Central Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Offside Front Axle king pin is loose in the axle beam (5.1.2 (d) (i))

MOT #16

2022-02-18 09:14

MOT test number

600449692006

Result**✓ Passed**

- Advice** Brake hose has slight corrosion to ferrule all (1.1.12 (f) (i))
- Advice** Brake pipe corroded, covered in grease or other material all (1.1.11 (c))
- Advice** Vehicle undersealed
- Advice** Nearside Front Lower Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Slight corrosion to underside including suspension components



MOT #15	2021-03-01 15:34
MOT test number	942252557287
Result	✓ Passed
Advice	Under body wax oiled

MOT #14	2021-03-01 14:36
MOT test number	968583153453
Result	✗ Failed
Fail	Offside Front Body mounting fixings insecure such that stability is seriously impaired central holed (6.2.2 (c) (ii))

MOT #13	2021-02-23 16:08
MOT test number	620942037144
Result	✗ Failed
Fail	Offside Front Body mounting fixings insecure such that stability is seriously impaired holed under headlight (6.2.2 (c) (ii))
Fail	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
Fail	Offside Front Body mounting fixings insecure such that stability is seriously impaired central holed (6.2.2 (c) (ii))
Fail	Nearside Front Body mounting fixings insecure such that stability is seriously impaired holed under headlights (6.2.2 (c) (ii))
Fail	Service brake efficiency below requirements (1.2.2 (a) (i))
Advice	Whole underside waxoiled
Fail	Nearside Front Body mounting fixings insecure such that stability is seriously impaired central holed (6.2.2 (c) (ii))

MOT #12	2020-09-11 08:25
MOT test number	341115528099
Result	✓ Passed
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Rear service brake low effort

**MOT #11** 2019-09-18 10:59**MOT test number** 462926500879**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #10** 2018-09-17 15:17**MOT test number** 106687538170**Result** ✓ Passed**MOT #9** 2017-09-15 12:48**MOT test number** 146591685744**Result** ✓ Passed**MOT #8** 2016-09-14 10:47**MOT test number** 147007400364**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Exhaust showing signs of corrosion**MOT #7** 2015-09-15 13:25**MOT test number** 519063646086**Result** ✓ Passed**Advice** Brake pipes showing signs of corrosion**Advice** Vehicle structure has slight corrosion (6.1.B.2)



MOT #6	2014-09-17 11:57
---------------	------------------

MOT test number	376790464224
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2013-09-17 15:15
---------------	------------------

MOT test number	346150563434
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2013-09-12 09:44
---------------	------------------

MOT test number	227675953271
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Offside Rear Shock absorber has a serious fluid leak (2.7.3)
-------------	--

Fail	Nearside front brake binding (3.7.B.1)
-------------	--

MOT #3	2012-09-20 15:53
---------------	------------------

MOT test number	105324962239
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2011-07-28 13:40
---------------	------------------

MOT test number	108309301243
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2010-09-14 09:00
---------------	------------------

MOT test number	934927950233
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
8 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	8 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	ND57SZG
Plate since	2019-09-29
Current registration	ND57SZG
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-28
Last registration	2023-08-09
Complete history	See info



Registration #1	2007-09-28	18 mi
Registration #2	2010-09-14	7.439 mi
Registration #3	2011-07-28	9.053 mi
Registration #4	2012-09-20	11.006 mi
Registration #5	2013-09-12	13.114 mi
Registration #6	2013-09-17	13.121 mi
Registration #7	2014-09-17	18.330 mi
Registration #8	2015-09-15	23.288 mi
Registration #9	2016-09-14	28.381 mi
Registration #10	2017-09-15	33.621 mi
Registration #11	2018-09-17	38.945 mi
Registration #12	2019-09-17	44.269 mi
Registration #13	2020-09-17	49.593 mi
Registration #14	2021-09-17	54.917 mi
Registration #15	2022-09-17	60.241 mi
Registration #16	2023-09-17	65.565 mi
Registration #17	2024-09-17	70.889 mi
Registration #18	2025-09-17	76.213 mi
Registration #19	2026-09-17	81.537 mi
Registration #20	2027-09-17	86.861 mi
Registration #21	2028-09-17	92.185 mi

More info >



Dimensions & weight

Width	1600 mm
Height	1705 mm
Length	3665 mm
Wheel base	2250 mm
Kerb weight	1150 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	M13A-1886782