



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI T SPIRIT
Colour	Black
Year of manufacture	2006
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.8 mpg
Consumption combined	40.3 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-11-01
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-30
Pictures	60
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-09-06
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	21
Total items failed	14

MOT #20	2022-09-01 14:35
MOT test number	891426176730
Result	✓ Passed
Next expiry date	2023-09-06
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Coil spring corroded Both (5.3.1 (b) (i))
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #19	2022-08-31 07:44
MOT test number	891038523342
Result	✗ Failed
Fail	Offside Front Suspension arm corroded and seriously weakened Holed (5.3.3 (b) (i))
Advice	Rear Coil spring corroded Both (5.3.1 (b) (i))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #18** 2021-08-12 08:08**MOT test number** 710405347261**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #17** 2020-09-04 09:23**MOT test number** 991512016509**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2019-09-07 16:06**MOT test number** 772565607537**Result** ✓ Passed**MOT #15** 2019-09-07 16:06**MOT test number** 145088331195**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp(s) all not working (4.3.1 (a) (iii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #14** 2018-09-07 09:58**MOT test number** 991728090047**Result** ✓ Passed**MOT #13** 2017-09-04 12:44**MOT test number** 180839118573**Result** ✓ Passed**Advice** Both rear coil springs corroded

**MOT #12** 2017-09-01 15:25**MOT test number** 388719796819**Result** ✗ Failed**Fail** Brake pedal creeps down when held under pressure (3.3.B.1a)**Advice** Both rear coil springs corroded**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**MOT #11** 2016-08-19 11:36**MOT test number** 123658580499**Result** ✓ Passed**Advice** O/s and n/s rear brake pipes corroded**Advice** Small split on end of o/s/f wiper blade**Advice** Nearside Front tyre worn on outer edge**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #10** 2015-08-27 14:47**MOT test number** 105835834869**Result** ✓ Passed**MOT #9** 2014-08-20 12:24**MOT test number** 786722134226**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #8** 2014-08-20 10:56**MOT test number** 995452134262**Result** ✗ Failed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Front registration plate delaminated (6.3.1d)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #7** 2013-08-15 16:37**MOT test number** 336927523297**Result** ✓ Passed**MOT #6** 2013-08-15 09:02**MOT test number** 909607823242**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Inner Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Inner Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside rear brake binding (3.7.B.1)**MOT #5** 2012-08-21 12:35**MOT test number** 645224632213**Result** ✓ Passed**Notice** Slight drag on o/s/f brake**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #4	2011-08-23 14:11
MOT test number	165375531251
Result	✓ Passed
MOT #3	2010-08-18 17:10
MOT test number	194460330224
Result	✓ Passed
MOT #2	2010-08-18 12:59
MOT test number	513920530208
Result	✗ Failed
<div><div>Fail</div>Front Brake pad(s) less than 1.5 mm thick (3.5.1g)</div>	
MOT #1	2009-08-28 13:19
MOT test number	720440149281
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
4 October 2022

X

MOT

Expired:
6 September 2023

Tax status	Expired at 4 October 2022
Days left	573 days too late
MOT expiry date	6 September 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	BV56BKF
Plate since	2019-09-28
Current registration	BV56BKF
Plate since	2019-09-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-09-01
Last registration	2022-09-01
Complete history	See info



Registration #1	2006-09-01	25 mi
Registration #2	2009-08-28	24.637 mi
Registration #3	2010-08-18	31.414 mi
Registration #4	2010-08-18	31.414 mi
Registration #5	2011-08-23	38.377 mi
Registration #6	2012-08-21	45.135 mi
Registration #7	2013-08-15	51.148 mi
Registration #8	2013-08-15	51.148 mi
Registration #9	2014-08-20	56.418 mi
Registration #10	2014-08-20	56.418 mi
Registration #11	2015-08-27	61.324 mi
Registration #12	2016-08-19	65.591 mi
Registration #13	2016-08-19	65.591 mi
Registration #14	2016-08-19	65.591 mi
Registration #15	2016-08-19	65.591 mi
Registration #16	2016-08-19	65.591 mi
Registration #17	2016-08-19	65.591 mi
Registration #18	2016-08-19	65.591 mi
Registration #19	2016-08-19	65.591 mi
Registration #20	2016-08-19	65.591 mi
Registration #21	2016-08-19	65.591 mi
Registration #22	2016-08-19	65.591 mi
Registration #23	2016-08-19	65.591 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1220 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3ZZU778649