



report date: 2024-03-29

General information

Make	VAUXHALL
Model	MOVANO 3300 MWB H/R P/V CDTI (100BHP)
Colour	White
Year of manufacture	2006
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	260 Nm at 1.500 rpm
Engine capacity	2.463 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-19
Pictures	17
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-21
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	23
Total items failed	6

MOT #19 2023-08-22 14:46

MOT test number 663236210029

Result ✓ Passed

Next expiry date 2024-08-21

**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #18 2021-08-23 14:08

MOT test number 475079561154

Result ✓ Passed

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))



## MOT #17

2021-08-20 09:04

MOT test number

730949710671

## Result

✗ Failed

**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**Advice** Offside Rear tyre is over 10 years old**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MAJOR** Nearside Front Subframe mounting prescribed area excessively corroded significantly reducing structural strength box section (5.3.6 (a) (i))

## MOT #16

2020-10-09 10:24

MOT test number

175035112391

## Result

✓ Passed

## MOT #15

2019-10-09 12:07

MOT test number

301971917538

## Result

✓ Passed

**Advice** Exhaust mounting defective (6.1.2 (a))

**MOT #14** 2019-10-08 09:36**MOT test number** 244122930629**Result** ✗ Failed**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Offside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Nearside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))**Advice** Exhaust mounting defective (6.1.2 (a))**DANGEROUS** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #13** 2018-10-04 09:13**MOT test number** 725117916799**Result** ✓ Passed**MOT #12** 2017-10-09 10:04**MOT test number** 717481332723**Result** ✓ Passed**MOT #11** 2016-10-07 13:03**MOT test number** 846062188829**Result** ✓ Passed**MOT #10** 2016-10-06 09:37**MOT test number** 873336312462**Result** ✗ Failed**Fail** Hazard warning switch faulty (1.4.B.1d)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Rear Registration plate lamp not working (1.1.C.1d)



<b>MOT #9</b>	2015-10-08 09:59
---------------	------------------

<b>MOT test number</b>	302786049492
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #8</b>	2014-09-09 09:33
---------------	------------------

<b>MOT test number</b>	586062954230
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #7</b>	2013-09-16 08:36
---------------	------------------

<b>MOT test number</b>	999369053267
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2013-09-13 11:57
---------------	------------------

<b>MOT test number</b>	139596253212
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Rear Stop lamp not working (1.2.1b)
-------------	-------------------------------------

<b>MOT #5</b>	2012-09-13 10:10
---------------	------------------

<b>MOT test number</b>	847687852276
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2011-06-28 11:53
---------------	------------------

<b>MOT test number</b>	387339671115
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2010-07-01 16:58
---------------	------------------

<b>MOT test number</b>	793122580184
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



MOT #2	2009-07-02 15:52
MOT test number	760563689134
Result	✓ Passed

MOT #1	2009-07-02 11:30
MOT test number	212623489153
Result	✗ Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
21 August 2024

Tax status		Valid until 1 August
Days left		93
MOT expiry date		21 August 2024
Full MOT history		<a href="#">See MOT history</a>





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>SB06KWD</b>
Plate since	2019-03-29
Current registration	<b>SB06KWD</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-06-22
Last registration	2023-08-22
Complete history	<a href="#">See info</a>



Registration #1	2006-06-22	17 mi
Registration #2	2009-07-02	19.725 mi
Registration #3	2009-07-02	19.725 mi
Registration #4	2010-07-01	25.524 mi
Registration #5	2011-06-28	32.861 mi
Registration #6	2012-09-13	34.938 mi
Registration #7	2013-09-13	38.255 mi
Registration #8	2013-09-16	38.255 mi
Registration #9	2014-09-09	44.356 mi
Registration #10	2015-10-08	48.018 mi
Registration #11	2016-10-06	52.755 mi
Registration #12	2017-09-20	55.557 mi
Registration #13	2018-09-20	55.557 mi
Registration #14	2019-09-20	55.557 mi
Registration #15	2020-09-20	55.557 mi
Registration #16	2021-09-20	55.557 mi
Registration #17	2022-09-20	55.557 mi
Registration #18	2023-09-20	55.557 mi
Registration #19	2024-09-20	55.557 mi
Registration #20	2025-09-20	55.557 mi
Registration #21	2026-09-20	55.557 mi

More info >



Dimensions & weight

Width	2359 mm
Height	2493 mm
Length	5399 mm
Kerb weight	1863 kg
Max. allowed weight	3300 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C163107