



BA04LEW

report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE CLASSIC
Colour	Silver
Year of manufacture	2004
Top speed	125 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	325 Nm at 1.800 rpm
Engine capacity	1.988 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-09-04
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-25
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	57
Total items failed	19

MOT #24	2023-09-13 08:12
MOT test number	247262727951
Result	✓ Passed
Next expiry date	2024-09-25

MOT #23	2022-09-14 12:55
MOT test number	949942206199
Result	✓ Passed
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #22	2021-09-03 13:43
MOT test number	317489019189
Result	✓ Passed
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #21**

2021-09-03 10:50

MOT test number

138368154483

Result**✗ Failed**

- MAJOR** Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))
- MAJOR** Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Offside Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))

MOT #20

2020-09-26 10:12

MOT test number

268289673434

Result**✓ Passed****MOT #19**

2020-09-25 13:56

MOT test number

413546380446

Result**✗ Failed**

- DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))



MOT #182019-03-18 13:14

MOT test number538198451617

Result		✓ Passed
Advice	Both front head lamps starting to frost over	
Advice	Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush on to sumflame (5.3.4 (a) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))	
Advice	Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	
Advice	Items removed from driver's view prior to test	
Advice	Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))	

**MOT #17**

2019-03-18 11:59

MOT test number

990258839461

Result**✗ Failed**

Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush on to sumflame (5.3.4 (a) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Items removed from driver's view prior to test

Advice Offside Rear Coil spring corroded (5.3.1 (b) (ii))

MAJOR Brake fluid contaminated (1.8 (a))

DANGEROUS Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Both front head lamps starting to frost over

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

Advice Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

MOT #16

2018-04-06 07:59

MOT test number

783675990655

Result**✓ Passed**

Advice Front Inner brake disc worn, pitted or scored, but not seriously weakened edges (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Both rear tyres wearing on inner edges

**MOT #15** 2017-04-10 15:56**MOT test number** 481626616455**Result** ✓ Passed**MOT #14** 2017-04-08 11:27**MOT test number** 588927166781**Result** ✗ Failed

- Fail** Offside Headlamp aim too low (1.8)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Headlamp aim too low (1.8)
- Advice** Nearside Front tyre pressure low
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)

MOT #13 2016-03-12 09:46**MOT test number** 123764307669**Result** ✓ Passed

- Advice** Nearside Rear tyre worn away on inner edge
- Advice** Slight play in o/s rear suspension

MOT #12 2015-04-03 12:23**MOT test number** 989793295056**Result** ✓ Passed



MOT #11	2015-04-03 12:23
MOT test number	288753295012
Result	✗ Failed
Pass with rectification	Offside Headlamp not working on main beam (1.7.5a)

MOT #10	2014-03-31 14:16
MOT test number	237810294059
Result	✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
Notice	Both rear brake discs are worn/scored on inner faces
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
Notice	Both rear tyres centre tread 4mm, outer tread 3mm, inner tread worn smooth [LEGAL AT TEST]

**MOT #9**

2014-03-14 16:57

MOT test number

126243374431

Result**✗ Failed****Fail** Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Notice** Front brake discs are worn/pitted**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Rear brake application uneven (3.7.B.2)**Fail** Offside Headlamp aim too low and too far to the left. (1.8)**Fail** Offside Inner Front Fuel system component insecure (7.2.1)**Notice** Rear brake discs are scored/worn**Fail** Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Notice** Both rear tyres inner tread worn smooth [LEGAL AT TEST]**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Headlamp aim too low and too far to the right. (1.8)**MOT #8**

2013-03-15 17:07

MOT test number

108384473077

Result**✓ Passed****Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #7** 2012-03-15 13:44**MOT test number** 668775172061**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #6** 2010-09-30 14:50**MOT test number** 312543570442**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2009-09-08 12:46**MOT test number** 770681859227**Result** ✓ Passed**MOT #4** 2009-09-08 12:46**MOT test number** 264821259201**Result** ✗ Failed**Pass with rectification** Registration plate fitted to the front does not have black characters on a white background (6.3.2a)**MOT #3** 2008-09-19 14:12**MOT test number** 890933768210**Result** ✓ Passed**MOT #2** 2008-09-19 12:07**MOT test number** 204373668205**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #1	2007-08-24 11:43
MOT test number	211666637264
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
25 September 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	25 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	BA04LEW
Plate since	2019-09-28
Current registration	BA04LEW
Plate since	2019-09-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-07-19
Last registration	2023-09-13
Complete history	See info



Registration #1	2004-07-19	16 mi
Registration #2	2007-08-24	11.508 mi
Registration #3	2008-09-19	18.763 mi
Registration #4	2008-09-19	18.771 mi
Registration #5	2009-09-08	23.617 mi
Registration #6	2010-09-30	29.800 mi
Registration #7	2012-03-15	40.175 mi
Registration #8	2013-03-15	48.066 mi
Registration #9	2014-03-14	65.819 mi
Registration #10	2014-03-31	65.825 mi
Registration #11	2015-04-03	87.406 mi
Registration #12	2016-03-12	91.809 mi
Registration #13	2016-03-12	91.809 mi
Registration #14	2016-03-12	91.809 mi
Registration #15	2016-03-12	91.809 mi
Registration #16	2016-03-12	91.809 mi
Registration #17	2016-03-12	91.809 mi
Registration #18	2016-03-12	91.809 mi
Registration #19	2016-03-12	91.809 mi
Registration #20	2016-03-12	91.809 mi
Registration #21	2016-03-12	91.809 mi
Registration #22	2016-03-12	91.809 mi
Registration #23	2016-03-12	91.809 mi
Registration #24	2016-03-12	91.809 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0405281915126B