



report date: 2024-03-29

General information

Make	CITROEN
Model	C3 PICASSO BLUEHDI EDITION PICASSO
Colour	Purple
Year of manufacture	2016
Top speed	111 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	80.7 mpg
Consumption combined	72.4 mpg
CO2 emission	101 g/km
CO2 label	B





Internet history



Entry 2

Date	2023-12-05
Pictures	0
Listing price	<a href="#">View report</a>

source: carcraft.co.uk

Entry 1

Date	2022-01-07
Pictures	10
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-04
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	18
Total items failed	4

MOT #82023-10-05 12:48

MOT test number249230389116

Result✓ Passed

Next expiry date2024-10-04

- Advice

Front Suspension arm pin or bush worn but not resulting in excessive movement N/S + O/S (Splitting) (5.3.4 (a) (i))
- Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Offside Front Macpherson strut top bush or bearing has slight wear or free play
- Advice

Rear Exhaust mounting defective (6.1.2 (a))

**MOT #7**

2023-09-29 08:32

**MOT test number**

742735740768

**Result****✗ Failed****Fail** Windscreen washer not working (3.5 (a))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement N/S + O/S (Splitting) (5.3.4 (a) (i))**Advice** Offside Front Macpherson strut top bush or bearing has slight wear or free play**MOT #6**

2022-09-27 11:45

**MOT test number**

584913782739

**Result****✓ Passed****Advice** Rear Exhaust mounting defective Back box (6.1.2 (a))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement N/S+O/S(Starting to split) (5.3.4 (a) (i))**MOT #5**

2021-09-10 10:57

**MOT test number**

514230997938

**Result****✓ Passed****MOT #4**

2021-09-10 10:57

**MOT test number**

560140772024

**Result****✗ Failed****Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #3** 2020-09-18 12:18**MOT test number** 415010235577**Result** ✓ Passed**MOT #2** 2020-09-18 08:35**MOT test number** 929255845070**Result** ✗ Failed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #1** 2019-09-20 12:29**MOT test number** 688017099855**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
4 October 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	215
<b>MOT expiry date</b>	4 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-09-30
Last registration	2023-10-05
Complete history	<a href="#">See info</a>



Registration #1	2016-09-30	11 mi
Registration #2	2019-09-20	22.139 mi
Registration #3	2020-09-18	29.170 mi
Registration #4	2020-09-18	29.170 mi
Registration #5	2021-09-10	33.654 mi
Registration #6	2021-09-10	33.654 mi
Registration #7	2023-10-05	33.654 mi
Registration #8	2023-10-05	33.654 mi
Registration #9	2023-10-05	33.654 mi
Registration #10	2023-10-05	33.654 mi
Registration #11	2023-10-05	33.654 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBHA3137763