





report date: 2024-03-29

General information

Make	FIAT
Model	GRAND PUNTO ELEGANZA
Colour	Blue
Year of manufacture	2008
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	134 g/km
CO2 label	E



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2025-01-09
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	10
Total items failed	9

MOT #20	2024-01-09 11:18
MOT test number	850841502030
Result	✓ Passed
Next expiry date	2025-01-09

MOT #19	2023-01-10 12:07
MOT test number	928680459740
Result	✓ Passed

MOT #18	2023-01-10 12:07
MOT test number	451781345916
Result	▼ Failed
Pass with rectification (4.1.2 (c))	Nearside Front Headlamp aim projected beam image is obviously incorrect
Pass with rectification	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2
(c))	

MOT #17	2022-01-07 10:55
MOT test number	895909903550
Result	✓ Passed

CarCheck.co.uk page 2/12



Result

PY08LUJ report date: 2024-03-29

MOT #16 2022-01-07 10:55 **MOT** test number 133325794322 Result × Failed **Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #15 2021-02-10 11:44 **MOT** test number 133575535508 Result ✓ Passed **Advice** Front subframe corroded **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2020-06-17 10:43 **MOT** test number 965466602996 Result ✓ Passed **MOT #13** 2020-06-17 09:31 **MOT** test number 844150190659

× Failed Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #12 2020-03-11 09:47 774715336441 **MOT test number** Result ✓ Passed

MOT #11 2019-03-18 15:42 **MOT** test number 821954586664 Result ✓ Passed

CarCheck.co.uk page 3/12



MOT #10 2019-03-18 09:55

MOT test number 613045323944

Result X Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Front Macpherson strut pin or bush excessively worn top strut bearing excessively noise on lock to lock (5.3.4 (a) (i))

MOT #9 2018-03-20 12:28

MOT test number 682566955635

Result
✓ Passed

MOT #8 2018-03-20 11:29

MOT test number 688293158073

Result X Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #7 2017-03-17 14:11

MOT test number 260926781610

Result / Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #6 2016-03-18 14:16

MOT test number 419923158899

Advice Advise n/s/f tyre bald on edges.

CarCheck.co.uk page 4/12



MOT test number

Result

Fail Nearside Front coil spring broken (2.4.C.1a)

Advice Advise n/s/f tyre bald on edges.

MOT #4	2014-06-05 11:05
MOT test number	225866454413
Result	√ Passed
MOT #3	2013-06-13 11:58
MOT test number	658364863128
Result	√ Passed
Notice Coolant leak	

MOT #2	2012-06-14 10:29
MOT test number	295076062498
Result	✓ Passed
Notice Coolant leak	

MOT #1	2011-05-20 11:58
MOT test number	768340941101
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	9 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
manage of the same	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-07-09
Last registration	2024-01-09
Complete history	See info



Registration #1	2008-07-09	28 mi
Registration #2	2011-05-20	15.209 mi
Registration #3	2012-06-14	18.952 mi
Registration #4	2013-06-13	21.333 mi
Registration #5	2014-06-05	23.450 mi
Registration #6	2016-03-17	28.419 mi
Registration #7	2016-03-18	28.419 mi
Registration #8	2017-03-17	31.634 mi
Registration #9	2018-03-20	35.093 mi
Registration #10	2018-03-20	35.093 mi
Registration #11	2019-03-18	37.482 mi
Registration #12		11.117 es
Registration #13		11.777 es
Registration #14		11.117 es
Registration #15		11.777 es
Registration #16		11.117 es
Registration #17		11.777 es
Registration #18		11.117 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		D.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1.	2/12

Number of axles2Engine number4374300