



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	MATRIX GSI
Colour	Grey
Year of manufacture	2008
Top speed	105 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	141 Nm at 4.500 rpm
Engine capacity	1.599 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	42.8 mpg
Consumption combined	35.3 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-03
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-07-25
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	14
Total items failed	5

MOT #15 2023-06-27 11:51**MOT test number** 105897638872**Result** Passed**Next expiry date** 2024-07-25**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #14** 2022-07-04 14:12**MOT test number** 225153424280**Result** Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #13**

2022-07-01 12:05

MOT test number

623007209513

Result**✗ Failed****Advice**

Offside Rear Child Seat fitted not allowing full inspection of adult belt

Minor

Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice

Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))

Fail

Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail

Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Minor

Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice

Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail

Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #12

2021-07-26 11:52

MOT test number

410746302584

Result**✓ Passed****MOT #11**

2020-07-06 13:34

MOT test number

919924474348

Result**✓ Passed****MOT #10**

2020-07-06 13:34

MOT test number

541917307906

Result**✗ Failed****Pass with rectification**Obligatory mirror does not provide a view to the rear N/S DOOR MIRROR.
REPLACEMENT MIRROR STUCK ON. (3.3 (c))



MOT #9	2019-07-08 13:27
MOT test number	345066427528
Result	✓ Passed
MOT #8	2018-06-21 13:42
MOT test number	136214837290
Result	✓ Passed
MOT #7	2017-07-11 14:13
MOT test number	231540155413
Result	✓ Passed
MOT #6	2016-07-18 13:54
MOT test number	596400480837
Result	✓ Passed
MOT #5	2015-07-20 14:46
MOT test number	884775488812
Result	✓ Passed
MOT #4	2014-07-14 11:17
MOT test number	519485794114
Result	✓ Passed
MOT #3	2013-07-18 11:50
MOT test number	235599393165
Result	✓ Passed
MOT #2	2012-10-29 10:56
MOT test number	158553502343
Result	✓ Passed



MOT #1	2011-10-31 16:02
MOT test number	389194701390
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
25 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	25 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	BT08EVF
Plate since	2019-03-28
Current registration	BT08EVF
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-07-31
Last registration	2023-06-27
Complete history	See info



Registration #1	2008-07-31	23 mi
Registration #2	2011-10-31	14.871 mi
Registration #3	2012-10-29	21.199 mi
Registration #4	2013-07-18	24.478 mi
Registration #5	2014-07-14	30.163 mi
Registration #6	2015-07-20	35.572 mi
Registration #7	2016-07-18	40.438 mi
Registration #8	2017-07-11	44.657 mi
Registration #9	2018-06-21	47.584 mi
Registration #10	2019-06-20	50.511 mi
Registration #11	2020-06-19	53.438 mi
Registration #12	2021-06-18	56.365 mi
Registration #13	2022-06-17	59.292 mi
Registration #14	2023-06-16	62.219 mi
Registration #15	2024-06-15	65.146 mi
Registration #16	2025-06-14	68.073 mi
Registration #17	2026-06-13	70.999 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1740 mm
Height	1625 mm
Length	4025 mm
Wheel base	2600 mm
Kerb weight	1327 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	G4ED7T013093