





report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	Black
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg



CarCheck.co.uk page 1/11



## Internet history

### Entry 1

Date 2022-02-23

Pictures 73

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



PJ62NGG

report date: 2024-03-29

Passed

#### **MOT** history

Result

 MOT #10
 2023-01-14 12:10

 MOT test number
 396108220359

 Result
 ✓ Passed

Next expiry date 2024-01-19

Advice Offside Rear Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

 MOT #9
 2022-01-08 12:32

 MOT test number
 332587883649

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2020-12-21 15:35

MOT test number 705242648901

**Result** ✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #7 2020-12-21 09:06

**MOT test number** 921439347262

Result × Failed

**Advice** Nearside Rear Nail in tyre

**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Offside Front Tyre tread depth below requirements of 1.6mm 235/55/18 (5.2.3 (e))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 235/55/18 (5.2.3 (e))

CarCheck.co.uk page 3/11



MOT #6 2020-01-06 13:17

**MOT test number** 225345435876

**Result** ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Tire perishing in treads and sidewalls,

235/55-18. (5.2.3 (d) (ii))

**Advice** Advise oil leak, engine.

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Tire tread at 2.58mm, 235/55-18. (5.2.3

(e))

MOT #5 2019-01-03 08:35

**MOT test number** 923598491222

**Result** ✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge advise replacement (5.2.3 (e))

**MOT #4** 2018-01-10 08:28

**MOT test number** 847994514005

Result 

Passed

**Advice** Offside Power steering component(s) has slight seepage from a component rack area (2.3.3b)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2016-12-29 15:28

**MOT test number** 667479203527

Advice Nearside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)

CarCheck.co.uk page 4/11



Result

PJ62NGG report date: 2024-03-29

× Failed

MOT #2 2016-01-20 11:23

MOT test number 852722047647

**Result** 
✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit 2.0mm (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit 2.0mm (4.1.E.1)

**MOT #1** 2016-01-19 14:40

**MOT test number** 417535570007

Pass with rectification Offside Stop lamp not working (1.2.1b)

Advice Nearside Front Tyre worn close to the legal limit 2.0mm (4.1.E.1)

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Pass with rectification** Nearside Stop lamp not working (1.2.1b)

**Pass with rectification** Registration plate lamp not working (1.1.C.1d)

**Advice** Offside Front Tyre worn close to the legal limit 2.0mm (4.1.E.1)

**Pass with rectification** Inner Obligatory mirror missing (8.1.1)

Fail Nearside Windscreen wiper not operating automatically when switched on (8.2.1b)

CarCheck.co.uk page 5/11



PJ62NGG

report date: 2024-03-29

#### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date
Category
Type

Damage 2

Date

Category

**Type** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



PJ62NGG

report date: 2024-03-29

More info >

## Owner history

owner mistery	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	
Current registration	IIK NE
Plate since	
Current registration	NK SIE
Plate since	

CarCheck.co.uk page 8/11



#### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-01-17
Last registration	2023-01-14
Complete history	See info



Registration #1	2013-01-17	22 mi
Registration #2	2016-01-19	43.482 mi
Registration #3	2016-01-20	43.482 mi
Registration #4	2016-12-29	51.474 mi
Registration #5	2018-01-10	58.897 mi
Registration #6	2019-01-03	66.890 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 au

More info >

CarCheck.co.uk page 10/11



## Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

## Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ

CarCheck.co.uk page 11/11