





report date: 2024-03-29

General information

Make	CITROEN
Fidico	
Model	C4 PICASSO BLUEHDI FEEL S/S EAT6
Colour	Red
Year of manufacture	2017
Top speed	117 mph
0 - 60 mph	11.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	100 g/km
CO2 label	Α



CarCheck.co.uk page 1/11




Internet history

Entry 2

Date 2021-08-24

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-09-21
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	12
Total items failed	1

MOT #8	2023-09-22 11:37
MOT test number	345385850867
Result	✓ Passed
Next expiry date	2024-09-21

MOT #7	2022-09-16 09:07
MOT test number	630903148998
Result	✓ Passed

MOT #6	2022-09-14 11:46
MOT test number	188501521234
Result	X Failed

MAJOR Nearside Headlamp insecure mounts broken (4.1.1 (c))

MAJOR Nearside Headlamp aim too high (4.1.2 (a))

Pass with rectification Windscreen washer provides insufficient washer liquid empty (3.5 (a))

MOT #5	2021-08-28 13:22
MOT test number	630676371573
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



MOT #4 2021-08-28 13:03

MOT test number 693270513057

Result X Failed

MAJOR Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3 2021-02-09 14:29

MOT test number 404107122157

MOT #2 2020-09-17 13:39

MOT test number 651189311366

Result \(\sqrt{Passed} \)

Advice Nearside Front Tyre slightly damaged/cracking or perishing badly perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing badly perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing badly perishing (5.2.3 (d) (ii))

MOT #1 2020-09-17 11:23

MOT test number 916107789332

Result × Failed

Advice Nearside Front Tyre slightly damaged/cracking or perishing badly perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing badly perishing (5.2.3 (d) (ii))

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords

(5.2.3 (d) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing badly perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



KU17SMZ

report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is		OEN
PROFESSOR		

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	NIE UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-08-25
Last registration	2023-09-22
Complete history	See info



Registration #1	2017-08-25	18 mi
Registration #2	2020-09-17	7.631 mi
Registration #3	2020-09-17	7.631 mi
Registration #4	2021-02-09	8.022 mi
Registration #5		11.777 es
Registration #6		71.777 es
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		11.777 esi
Registration #10		11.777 es

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	***	
-------------	-----	--

Video <u>see crash video</u>

Dimensions & weight

Width	1826 mm
Height	1625 mm
Length	4428 mm
Wheel base	2785 mm
Kerb weight	1320 kg
Max. allowed weight	1975 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBHD3066007

CarCheck.co.uk page 11/11