



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D2 R-DESIGN
Colour	Grey
Year of manufacture	2010
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 2

Date	2022-07-21
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 1

Date	2022-06-28
Pictures	8
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2025-04-18
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	34
Total items failed	8

MOT #16 2024-04-10 14:36**MOT test number** 834274370127**Result** ✓ Passed**Next expiry date** 2025-04-18**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2024-04-10 07:54**MOT test number** 721808990745**Result** ✗ Failed**Fail** Nearside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Heavy grease leakage (6.1.7 (g) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2023-04-19 08:46**MOT test number** 757141788501**Result** ✓ Passed

**MOT #13**

2022-03-08 14:18

MOT test number

643339616632

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement inner / rear (5.3.4 (a) (i))
- Minor** Offside Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement inner / rear (5.3.4 (a) (i))

MOT #12

2021-03-11 14:36

MOT test number

382534426407

Result

✓ Passed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Minor** Battery insecure but not likely to fall from carrier top clamp (4.13 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded lower part (5.3.1 (b) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #11**

2021-03-09 11:36

MOT test number

148622051450

Result**✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Minor** Battery insecure but not likely to fall from carrier top clamp (4.13 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Offside Rear Coil spring corroded lower part (5.3.1 (b) (i))**MOT #10**

2020-03-03 15:48

MOT test number

420569804851

Result**✓ Passed****Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge inner edge worn (5.2.3 (e))**MOT #9**

2020-02-20 13:40

MOT test number

164485692454

Result**✗ Failed****Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge inner edge worn (5.2.3 (e))

**MOT #8** 2018-10-12 14:26**MOT test number** 700815331561**Result** ✓ Passed**Advice** Both rear tyres wearing unevenly on the inside edge**MOT #7** 2018-10-12 08:43**MOT test number** 205700773539**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Both rear tyres wearing unevenly on the inside edge**MOT #6** 2017-09-21 15:34**MOT test number** 324089959160**Result** ✓ Passed**MOT #5** 2016-09-29 11:20**MOT test number** 934922414310**Result** ✓ Passed**MOT #4** 2015-09-21 13:45**MOT test number** 389679381815**Result** ✓ Passed**Advice** Under trays and engine covers fitted**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2014-10-07 09:38
MOT test number	827020084207
Result	✓ Passed

MOT #2	2014-10-06 12:27
MOT test number	735299574223
Result	✗ Failed
Fail	Parking brake lever has no reserve travel (3.1.6b)

MOT #1	2013-09-23 11:24
MOT test number	109216363234
Result	✓ Passed
Notice	Damage to near side front side wall



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
18 April 2025

Tax status	Valid until 1 May
Days left	1
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-10-20
Last registration	2024-04-10
Complete history	See info



Registration #1	2010-10-20	17 mi
Registration #2	2013-09-23	26.677 mi
Registration #3	2014-10-06	33.321 mi
Registration #4	2014-10-07	33.322 mi
Registration #5	2015-09-21	39.715 mi
Registration #6	2016-09-29	45.732 mi
Registration #7	2017-09-21	51.775 mi
Registration #8	2018-10-12	74.347 mi
Registration #9	2018-10-12	74.347 mi
Registration #10	2020-02-20	91.012 mi
Registration #11	2020-05-20	91.012 mi
Registration #12	2020-05-20	91.012 mi
Registration #13	2020-05-20	91.012 mi
Registration #14	2020-05-20	91.012 mi
Registration #15	2020-05-20	91.012 mi
Registration #16	2020-05-20	91.012 mi
Registration #17	2020-05-20	91.012 mi
Registration #18	2020-05-20	91.012 mi
Registration #19	2020-05-20	91.012 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1361361