





### General information

| Make                | ΤΟΥΟΤΑ         |
|---------------------|----------------|
| Model               | C-HR ICON      |
| Colour              | Silver         |
| Year of manufacture | 2018           |
| Top speed           | 118 mph        |
| 0 - 60 mph          | 10.9 seconds   |
| Gearbox             | 6 speed Manual |

### Engine & fuel consumption

| Power                   | 114 BHP             |  |
|-------------------------|---------------------|--|
| Max. torque             | 185 Nm at 4.000 rpm |  |
| Engine capacity         | 1.197 cc            |  |
| Cylinders               | 4                   |  |
| Fuel type               | Petrol              |  |
| Consumption city        | 40.9 mpg            |  |
| Consumption extra urban | 53.3 mpg            |  |
| Consumption combined    | 2.8 mpg             |  |
| CO2 emission            | 135 g/km            |  |
| CO2 label               | E                   |  |







### Internet history

Entry 1

Date Pictures 2021-05-28

18

Listing price

View report









source: theaa.com



### MOT history

| MOT expiry date    | 2025-03-11 |
|--------------------|------------|
| MOT pass rate      | 57 %       |
| MOT passed         | 4          |
| Failed MOT tests   | 3          |
| Total advice items | 6          |
| Total items failed | 5          |

| MOT #7           | 2024-02-16 14:05 |
|------------------|------------------|
| MOT test number  | 122116616459     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-03-11       |

| MOT #6   |   | 2023-02-24 13:24 |
|----------|---|------------------|
| MOT test | number  | 765270674406     |
| Result   |   | ✓ Passed         |
| Advice   | Temporary puncture repair offside rear tyre                                 |                  |
| Advice   | Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) |                  |

| MOT #5   | 2023-02-24 13:24   |  |
|--|--|--|
| MOT test number                                    | 810325947405   |  |
| Result   | × Failed   |  |
| <b>Pass with rectification</b> (h))                | Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 |  |
| Advice Temporary puncture repair offside rear tyre |  |  |
| Advice Rear Registratio                            | n plate deteriorated but not likely to be misread (0.1 (b))                    |  |





| MOT #4   |   | 2022-03-08 12:07 |
|--|---|------------------|
| MOT test number  |   | 969034788095     |
| Result   |   | ✓ Passed         |
| Minor Offside Windscreen wiper blade defective (3.4 (b) (i))                                     |   |                  |
|  |   |                  |
| MOT #3   |   | 2022-03-08 12:07 |
| MOT test number  |   | 970220760526     |
| Result   |   | 🗙 Failed         |
| Pass with rectification  | Offside Headlamp aim too low Adjusted at test centre (4.1.2 ( | a))              |
| Minor Offside Windscreen wiper blade defective (3.4 (b) (i))                                     |   |                  |
| <b>Pass with rectification</b> Nearside Headlamp aim too low Adjusted at test centre (4.1.2 (a)) |   |                  |

| MOT #2          | 2021-02-20 11:03 |
|-----------------|------------------|
| MOT test number | 581875131171     |
| Result          | ✓ Passed         |

| MOT #1                  | 2021-02-20 11:03  |  |
|-------------------------|---|--|
| MOT test number         | 146267526089  |  |
| Result                  | × Failed  |  |
| Pass with rectification | Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |  |
| Pass with rectification | Offside Front Direction indicator not working (4.4.1 (a) (ii))                  |  |



Tax & MOT check

| ✓<br>Taxed<br>Tax due:<br>1 June 2024 | ✓<br>MOT<br>Expires:<br>11 March 2025 |
|---------------------------------------|---------------------------------------|
| Tax status                            | Valid until 1 June                    |
| Days left                             | 33                                    |
| MOT expiry date                       | 11 March 2025                         |
| Full MOT history                      | See MOT history                       |

### Tax calculation

| Vehicle class                 | 48         |
|-------------------------------|------------|
| Band                          | н          |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months)     | £ 180,00,- |
| Standard rate (6 months)      | £ 99,00,-  |
| Premium rate (12 months)      | £ 570,00,- |
| Premium rate (6 months)       | £ 313,50,- |





#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |      |
|----------|------|
| Date     |      |
| Category | Lamp |
| Туре     | K K  |
| Damage 2 | AMPL |
|          |      |
| Date     | NE   |
| Category | AMP  |
| Туре     |      |

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4        |

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec |             |
|--|-------------|
| **********   |             |
| ********   |             |
| *******  |             |
| **********   |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this TOYOTA had different number plates.  |             |
| Number of plates   | ,           |
| Carrent registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |
|  |             |





#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info  $\rightarrow$ 





## Mileage check

| Odometer                   | In miles        |
|----------------------------|-----------------|
| Mileage registrations      | 9               |
| First mileage registration | 2018-03-12      |
| Last registration          | 2024-02-16      |
| Complete history           | <u>See info</u> |



| Registration #1 | 2018-03-12 | 21 mi      |
|-----------------|------------|------------|
| Registration #2 | 2021-02-20 | 77.238 mi  |
| Registration #3 | 2021-02-20 | 77.238 mi  |
| Registration #4 |            | 11.777 esi |
| Registration #5 | 2022-03-08 | 80.459 mi  |
| Registration #6 |            | 11.777 esi |
| Registration #7 |            | 11.777 esi |
|                 |            |            |
| Registration #8 |            | 11.777 est |

More info >





### Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| 50482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 95%             |
| Children       | 77%             |
| Pedestrian     | 76%             |
| Safety systems | 78%             |
| Overall rating | 84%             |
| Video          | see crash video |



| Dimensions & weight               |                  |
|-----------------------------------|------------------|
| Width                             | 1795 mm          |
| Height                            | 1565 mm          |
| Length                            | 4360 mm          |
| Wheel base                        | 2640 mm          |
| Kerb weight                       | 1320 kg          |
| Max. allowed weight               | 1845 kg          |
| Additional information            |                  |
| Fuel tank capacity                | 43               |
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 5                |
| Number of seats<br>CarCheck.co.uk | 5 page 11/11     |

| Number of axles | 2          |
|-----------------|------------|
| Engine number   | 8NRU223463 |