





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO SE TSI
Colour	Grey
Year of manufacture	2019
Top speed	116 mph
0 - 100 km/h	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 kW / 95 HP / 94 BHP
Max. torque	175 Nm at 2.000 rpm
Engine capacity	999 сс
Cylinders	3
Fuel type	Petrol
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	52.3 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/10



report date: 2024-03-29

Internet history

Entry 1

Date	2022-05-11	
Pictures	1	
Listing price	View report	



source: cargurus.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-04-09
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	1
Total items failed	1

MOT #4	2024-04-03 11:26
MOT test number	969561412661
Result	✓ Passed
Next expiry date	2025-04-09

MOT #3	2024-04-02 16:27	
MOT test number	321331347498	
Result	× Failed	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords		
(5.2.3 (d) (i))		

MOT #2	2023-03-28 07:44
MOT test number	408303829128
Result	✓ Passed
MOT #1	2022-04-07 10:10

MOT #1	2022-04-07 10:10
MOT test number	150954945464
Result	✓ Passed

CarCheck.co.uk page 3/10



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	9 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 4/10



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.


Damage 1

Date	
Category	
Туре	
Damage 2	

Damage 2

Date
Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-29

More info >

Owner history

o mile. History	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	OK SIZ
Plate since	
Current registration	NK SIK
Plate since	

CarCheck.co.uk page 7/10



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 8/10



GL19VGO report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2019-04-10
Last registration	2024-04-03
Complete history	See info



Registration #1	2019-04-10	9 mi
Registration #2	2022-04-07	19.583 mi
Registration #3		11.777 es
Registration #4		71.777 66
Registration #5		11.777 es
Pogistration #6		

Registration #6

More info >

CarCheck.co.uk page 9/10



GL19VGO report date: 2024-03-29

Car features

S0225	Air conditionin
50295	
50482	
50501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	96%
Children	85%
Pedestrian	76%
Safety systems	59%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1751 mm
Height	1461 mm
Length	4053 mm
Wheel base	2551 mm
Kerb weight	1070 kg
Max. allowed weight	1610 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	page 10/10

CarCheck.co.uk page 10/10

Number of seats	5
Number of axles	2
Engine number	DKLA062185