




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TIGUAN R-LINE TECH TDI 4MOTION DSG
Colour	Grey
Year of manufacture	2019
Top speed	124 mph
0 - 100 km/h	9.3 seconds
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	55.4 mpg
Consumption combined	39.8 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 2


Date	2022-02-28
Pictures	22
Listing price	View report



source: yesauto.com

Entry 1

Date	2022-02-27
Pictures	23
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-21
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	5
Total items failed	5

MOT #5	2024-01-22 12:05
MOT test number	866080055859
Result	✓ Passed
Next expiry date	2025-01-21

MOT #4	2024-01-22 12:05
MOT test number	572326982787
Result	✗ Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

MOT #3	2023-01-19 12:02
MOT test number	684348938322
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2	2022-01-20 15:28
MOT test number	926962033790
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #1**

2022-01-17 08:47

MOT test number

461737999542

Result**✗ Failed****Fail**

Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail

Rear Service brake excessively fluctuating (1.2.1 (e))

Fail

Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail

Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
21 January 2025

Tax status	Valid until 1 May
Days left	366
MOT expiry date	21 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BL68ASV
Plate since	2019-09-29
Current registration	 BL68ASV
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2019-01-14
Last registration	2024-01-22
Complete history	See info



Registration #1	2019-01-14	6 mi
Registration #2	2022-01-17	68.796 mi
Registration #3	2022-01-20	68.796 mi
Registration #4	2023-01-20	68.796 mi
Registration #5	2023-01-20	68.796 mi
Registration #6	2023-01-20	68.796 mi
Registration #7	2023-01-20	68.796 mi
Registration #8	2024-01-22	68.796 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	84%
Pedestrian	72%
Safety systems	68%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2099 mm
Height	1654 mm
Length	4486 mm
Wheel base	2677 mm
Kerb weight	1673 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	60 l
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	DFGAB06843