





report date: 2024-03-28

General information

Make	BMW
Model	730 730 LD SE
Colour	Blue
Year of manufacture	2007
Top speed	148 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	228 BHP	
Max. torque	520 Nm at 2.000 rpm	
Engine capacity	2.993 сс	
Cylinders	6	
Fuel type	Diesel	
Consumption city	25.0 mpg	
Consumption extra urban	44.1 mpg	
Consumption combined	34.5 mpg	
CO2 emission	216 g/km	
CO2 label	K	



CarCheck.co.uk page 1/12



LV07UAC

report date: 2024-03-28

MOT history

MOT expiry date	2021-09-30
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	19
Total items failed	11

MOT #15		2020-10-01 16:29
MOT test	number	331085462222
Result		✓ Passed
Next expi	ry date	2021-09-30
Advice	Engine covers / floor under trays fitted unable to fully inspect all components	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #14	2020-10-01 08:11
MOT test number	392794509503
Result	× Failed
Fail Nearside Front Tyre has ply or cords exposed side wall cords showing (5.2.3 (d) (ii))	
Advice Engine covers / floor under trays fitted unable to fully inspect all components	
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #13	2019-06-21 13:32
MOT test number	572592519731
Result	✓ Passed
Advice Rear fuel tank damp	

CarCheck.co.uk page 2/12



LV07UAC

report date: 2024-03-28

MOT #12 2018-08-02 09:25

MOT test number 196638358515

Result
✓ Passed

MOT #11 2018-08-02 09:25

MOT test number 129000504393

Result ★ Failed

Pass with rectification Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))

Pass with rectification Headlamp aim too high (4.1.2 (a))

MOT #10 2017-04-25 12:04

MOT test number 635015463751

Result \rightarrow Passed

MOT #9 2017-04-24 16:06

MOT test number 162429798684

Result X Failed

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Pass with rectification Offside Headlamp aim too low (1.8)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #8 2016-02-26 16:24

MOT test number 298653147180

Result \rightarrow Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 3/12



LV07UAC

report date: 2024-03-28

MOT #7 2016-02-26 16:24

MOT test number 123331802009

Result X Failed

Pass with rectification Offside Front Headlamp aim too high (1.8)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Pass with rectification Nearside Front Headlamp aim too low (1.8)

MOT #6 2015-01-02 12:30

MOT test number 779402505009

Result ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2014-03-31 08:32

MOT test number 465000794072

Result

✓ Passed

MOT #4 2013-03-08 17:38

MOT test number 805677463000

Result \(\sqrt{Passed} \)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Notice Under-trays fitted obscuring some underside components

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/12



MOT #3 2013-03-08 17:30

MOT test number 159937163406

Result X Failed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Notice Under-trays fitted obscuring some underside components

Fail Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)

MOT #2 2012-02-03 16:31

MOT test number 288074032015

Result ✓ Passed

MOT #1 2010-11-04 12:01

MOT test number 304498900357

Result \rightarrow Passed

CarCheck.co.uk page 5/12



Tax & MOT check



X MOT

Tax expired: 1 March 2021 Expired: 30 September 2021

Tax status	Expired at 1 March 2021
Days left	1154 days too late
MOT expiry date	30 September 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1


Date

Category
Type

Damage 2

Date

Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report J	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	UK ZIS
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 10/12



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-07-27
Last registration	2020-10-01
Complete history	See info



Registration #1	2007-07-27	18 mi
Registration #2	2010-11-04	23.718 mi
Registration #3	2012-02-03	37.365 mi
Registration #4	2013-03-08	48.943 mi
Registration #5	2013-03-08	48.943 mi
Registration #6	2014-03-31	59.905 mi
Registration #7	2015-01-02	67.600 mi
Registration #8	2016-02-26	85.693 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1902 mm
Height	1484 mm
Length	5179 mm
Wheel base	3128 mm
Kerb weight	1900 kg
Max. allowed weight	2520 kg

Additional information

Fuel tank capacity	88 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles2Engine number24476437