



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 LOOK
Colour	Silver
Year of manufacture	-
Top speed	117 mph
Gearbox	4 speed Semi-Automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	38.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-08
Pictures	7
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history****MOT #17** 2022-04-06 13:03**MOT test number** 156443589566**Result** ✓ Passed**Next expiry date** 2023-04-05

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16** 2022-04-06 13:03**MOT test number** 903405310324**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2021-02-16 13:42**MOT test number** 523969578552**Result** ✓ Passed

**MOT #14** 2020-02-05 14:30**MOT test number** 109519034343**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #13** 2019-03-07 11:55**MOT test number** 910752616036**Result** ✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12** 2018-02-13 16:05**MOT test number** 669312688524**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Exhaust corroded

**MOT #11** 2018-02-13 09:52**MOT test number** 104257725739**Result** ✗ Failed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Exhaust system not adequately supported (7.1.1)
- Fail** Emissions not tested (7.3.A.1)
- Advice** Exhaust corroded

**MOT #10** 2017-03-03 10:19**MOT test number** 659912541284**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2016-03-01 15:42**MOT test number** 601993959191**Result** ✓ Passed**Advice** All brake discs slightly corroded**MOT #8** 2015-02-17 14:55**MOT test number** 236578845051**Result** ✓ Passed**Notice** Rear Back Box Outer Skin Corroded.**Notice** Front And Rear Discs Rusty On Inner Faces.**MOT #7** 2013-06-20 15:40**MOT test number** 818661473136**Result** ✓ Passed**MOT #6** 2013-06-20 09:00**MOT test number** 545021373169**Result** ✗ Failed**Fail** Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)

**MOT #5** 2012-06-25 09:05**MOT test number** 345407172142**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-07-01 16:19**MOT test number** 339602681194**Result** ✓ Passed**Notice** Offside front headlamp has lens cover/protector fitted**MOT #3** 2011-07-01 12:07**MOT test number** 578642581136**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Notice** Offside front headlamp has lens cover/protector fitted**Fail** Power steering component(s) leaking (2.3.3b)**MOT #2** 2010-07-05 08:54**MOT test number** 400326680133**Result** ✓ Passed**MOT #1** 2009-11-27 12:07**MOT test number** 612081439367**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	VK56XWH
Plate since	2019-09-29
Current registration	VK56XWH
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-11-28
Last registration	2022-04-06
Complete history	<a href="#">See info</a>



Registration #1	2006-11-28	9 mi
Registration #2	2009-11-27	10.023 mi
Registration #3	2010-07-05	12.279 mi
Registration #4	2011-07-01	16.077 mi
Registration #5	2011-07-01	16.077 mi
Registration #6	2012-06-25	20.427 mi
Registration #7	2013-06-20	24.472 mi
Registration #8	2013-06-20	24.475 mi
Registration #9	2015-02-17	28.392 mi
Registration #10	2016-03-01	30.093 mi
Registration #11	2016-03-01	30.093 mi
Registration #12	2016-03-01	30.093 mi
Registration #13	2016-03-01	30.093 mi
Registration #14	2016-03-01	30.093 mi
Registration #15	2016-03-01	30.093 mi
Registration #16	2016-03-01	30.093 mi
Registration #17	2016-03-01	30.093 mi
Registration #18	2016-03-01	30.093 mi
Registration #19	2016-03-01	30.093 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1673 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1125 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FX6Q3106148