



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	407 SPORT HDI
Colour	Grey
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-01
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history****MOT #16** 2021-07-29 13:41**MOT test number** 761391285059**Result** ✓ Passed**Next expiry date** 2022-07-28

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #15 2021-07-28 08:31**MOT test number** 756414433546**Result** ✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #14	2020-07-29 12:51
MOT test number	373326437776
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2020-07-10 10:53
MOT test number	170557405277
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge low to legal limit (5.2.3 (e))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt split (6.1.7 (g) (ii))
Fail	Nearside Rear Service brake excessively binding (1.2.1 (f))
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #12	2019-07-08 09:06
MOT test number	733873155743
Result	✓ Passed

MOT #11	2018-07-09 09:18
MOT test number	788804282128
Result	✓ Passed

MOT #10	2018-07-09 09:18
MOT test number	213896714287
Result	✗ Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #9** 2017-07-07 08:38**MOT test number** 813447550184**Result** ✓ Passed**MOT #8** 2017-07-07 08:38**MOT test number** 823744859651**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #7** 2016-07-08 13:55**MOT test number** 554054844708**Result** ✓ Passed**MOT #6** 2016-07-08 09:43**MOT test number** 957237794122**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm inner cords showing (4.1.E.1)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #5** 2015-07-09 08:57**MOT test number** 913722197629**Result** ✓ Passed**Advice** Under trays fitted not allowing full inspection of some underside components**MOT #4** 2014-07-07 10:51**MOT test number** 257748684186**Result** ✓ Passed



MOT #3	2013-07-08 13:50
MOT test number	587849483176
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Offside front fog lamp insecure

MOT #2	2012-07-10 15:50
MOT test number	865822092138
Result	✓ Passed

MOT #1	2011-06-29 13:34
MOT test number	325090181137
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-06-06
Last registration	2021-07-29
Complete history	See info



Registration #1	2008-06-06	29 mi
Registration #2	2011-06-29	17.772 mi
Registration #3	2012-07-10	21.983 mi
Registration #4	2013-07-08	28.561 mi
Registration #5	2014-07-07	50.116 mi
Registration #6	2015-07-09	73.567 mi
Registration #7	2016-07-08	95.251 mi
Registration #8	2016-07-08	95.252 mi
Registration #9	2017-07-07	116.247 mi
Registration #10	2018-06-29	138.217 mi
Registration #11	2019-06-29	159.217 mi
Registration #12	2020-06-29	180.217 mi
Registration #13	2021-06-29	201.217 mi
Registration #14	2022-06-29	222.217 mi
Registration #15	2023-06-29	243.217 mi
Registration #16	2024-06-29	264.217 mi
Registration #17	2025-06-29	285.217 mi
Registration #18	2026-06-29	306.217 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2

Engine number

DYUK4096137