



report date: 2024-03-29

General information

Make	MINI
Model	MINI (R60) COOPER S ALL4
Colour	White
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	42.2 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-10-24
Pictures	3
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-08-10
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-11
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	19
Total items failed	5

MOT #13 2023-08-02 15:00

MOT test number 429970542631

Result ✓ Passed

Next expiry date 2024-08-11

- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brake pipe corroded, covered in grease or other material Going into slave cylinder (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))
- Advice** Front Suspension arm corroded but not seriously weakened Both sides (5.3.3 (b) (i))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

MOT #12 2022-07-25 16:14

MOT test number 786907994874

Result ✓ Passed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Suspension arm corroded but not seriously weakened Both (5.3.3 (b) (i))

**MOT #11**

2022-07-20 10:55

MOT test number

296893279865

Result

✗ Failed

- Advice** Front Suspension arm corroded but not seriously weakened Both (5.3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10

2021-08-12 15:34

MOT test number

229721757369

Result

✓ Passed

- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9

2020-09-16 12:14

MOT test number

853624617581

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8

2019-09-20 11:26

MOT test number

908306787840

Result

✓ Passed

**MOT #7** 2019-09-10 09:16**MOT test number** 849634006206**Result** ✗ Failed**Fail** Offside Rear fog lamp does not emit a steady red light (4.5.4 (a))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #6** 2018-09-26 11:33**MOT test number** 380895068391**Result** ✓ Passed**MOT #5** 2017-09-28 08:40**MOT test number** 569495059987**Result** ✓ Passed**MOT #4** 2016-09-19 08:38**MOT test number** 479185214740**Result** ✓ Passed**MOT #3** 2016-09-19 08:38**MOT test number** 884054630228**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #2** 2015-09-23 09:57**MOT test number** 373696520458**Result** ✓ Passed



MOT #1	2014-09-23 15:47
MOT test number	277606364207
Result	✓ Passed



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-06-29
Current registration	
Plate since	2019-06-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-29
Last registration	2023-08-02
Complete history	See info



Registration #1	2011-09-29	18 mi
Registration #2	2014-09-23	34.885 mi
Registration #3	2015-09-23	46.731 mi
Registration #4	2016-09-19	52.725 mi
Registration #5	2016-09-19	52.725 mi
Registration #6	2017-09-28	58.435 mi
Registration #7	2018-09-26	65.090 mi
Registration #8	2019-09-10	69.235 mi
Registration #9	2020-09-29	75.277 mi
Registration #10	2021-09-29	81.319 mi
Registration #11	2022-09-29	87.361 mi
Registration #12	2023-08-02	93.403 mi
Registration #13	2023-08-02	93.403 mi
Registration #14	2023-08-02	93.403 mi
Registration #15	2023-08-02	93.403 mi
Registration #16	2023-08-02	93.403 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Kerb weight	1380 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

A574I961