




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	AMAROK DC TDI HIGHLINE 4MOTION
Colour	Grey
Year of manufacture	2015
Top speed	108 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	180 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	38.2 mpg
Consumption combined	35.3 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 2


Date	2022-02-11
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2022-01-23
Pictures	50
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-11-01
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	9
Total items failed	0

MOT #6	2023-11-02 11:58
MOT test number	395858166285
Result	✓ Passed
Next expiry date	2024-11-01

MOT #5	2022-05-19 13:42
MOT test number	904334512827
Result	✓ Passed

MOT #4	2021-03-17 12:25
MOT test number	551278893936
Result	✓ Passed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Minor	Offside Rear Electrical wiring inadequately secured from rear cab into body (4.11 (a) (i))

**MOT #3** 2021-03-11 14:09**MOT test number** 737562004545**Result** ✗ Failed

- Minor** Nearside Obligatory mirror slightly damaged mirror glass (3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edges. (5.2.3 (e))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Minor** Offside Rear Electrical wiring inadequately secured from rear cab into body (4.11 (a) (i))
- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Nearside Front Body component damaged and likely to cause injury wing mirror unit. (6.2.1 (a) (i))

MOT #2 2019-08-28 11:55**MOT test number** 864998802228**Result** ✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #1 2018-09-19 10:32**MOT test number** 855788846018**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
1 November 2024

Tax status	Valid until 1 May
Days left	1
MOT expiry date	1 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	AK65UTO
Plate since	2019-03-29
Current registration	AK65UTO
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-12-16
Last registration	2023-11-02
Complete history	See info



Registration #1	2015-12-16	24 mi
Registration #2	2018-09-19	55.255 mi
Registration #3	2019-08-28	69.939 mi
Registration #4	2021-03-11	89.229 mi
Registration #5	2021-03-17	89.229 mi
Registration #6	2023-05-20	95.277 mi
Registration #7	2023-05-20	95.277 mi
Registration #8	2023-05-20	95.277 mi
Registration #9	2023-05-20	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	64%
Pedestrian	47%
Safety systems	57%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	2228 mm
Height	1834 mm
Length	5254 mm
Wheel base	3000 mm
Kerb weight	2093 kg
Max. allowed weight	3170 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	5
Number of axles	2

