





report date: 2024-03-29

General information

Make	JAGUAR
Model	XJ V6 EXECUTIVE
Colour	Grey
Year of manufacture	-
Top speed	140 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	204 BHP
Max. torque	435 Nm at 1.900 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	26.2 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.9 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

2022-02-03 17:19

MOT test number 588271953134

Result
✓ Passed

Next expiry date 2023-02-02

MOT #14 2021-06-03 14:09

MOT test number 524679712199

Result \sqrt{Passed}

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13 2020-07-18 11:49

MOT test number 864237519766

MOT #12 2019-09-02 14:53

MOT test number 199394823088

Result ✓ Passed

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Different size tyres fitted front & rear

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Aero style wipers smearing

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

Advice Engine bay covered in oil?

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #11 2019-09-02 14:53

MOT test number 243263929640

Result X Failed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Engine bay covered in oil?

Advice Different size tyres fitted front & rear

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Windscreen washer not working (3.5 (a))

Advice Front Aero style wipers smearing

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2019-08-23 15:33

MOT test number 574236394801

Result × Failed

Advice Front Aero style wipers smearing

Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Engine bay covered in oil?

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Different size tyres fitted front & rear

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm 235/50R18 (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #9 2018-08-06 12:28

MOT test number 379820878565

MOT #8 2017-06-12 15:48

MOT test number 674529688733

Result

Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #7 2016-05-24 15:49

MOT test number 225336676350

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #6 2016-05-24 14:03

MOT test number 453690112580

Result X Failed

Fail Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Fail Offside Windscreen washer provides insufficient washer liquid (8.2.3)

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT #5 2015-03-24 16:28

MOT test number 525063485004

Result \(\sqrt{Passed} \)

Notice Unable to inspect centre brake/fuel pipes due to covers fitted

MOT #4 2014-02-07 10:27

MOT test number 136028034083

Result ✓ Passed

MOT #3 2013-04-23 16:31

MOT test number 677883513185

Result \rightarrow Passed

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #2 2013-04-19 09:00

MOT test number 118169903118

Result X Failed

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Offside Headlamp not working on dipped beam (1.7.5a)

Fail Offside Rear Lower Shock absorber has an excessively worn bush (2.7.4)

Fail Nearside Registration plate lamp not working (1.1.C.1d)

MOT #1 2012-05-23 14:35

MOT test number 725154042110

Result

Passed

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner his	tory
-----------	------

· ·		
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		AR
THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this JAGUAR had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-06-21
Last registration	2022-02-03
Complete history	See info



Registration #1	2008-06-21	28 mi
Registration #2	2012-05-23	35.969 mi
Registration #3	2013-04-19	44.826 mi
Registration #4	2013-04-23	44.836 mi
Registration #5	2014-02-07	50.858 mi
Registration #6	2015-03-24	63.441 mi
Registration #7	2016-05-24	74.041 mi
Registration #8	2016-05-24	74.041 mi
Registration #9	2017-06-12	83.572 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		9.70 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

		_		
luma	ncior	ור א.	MOIO	nt.
	ensior	ואט כו	WEIG	HL

Width	1898 mm
Height	1455 mm
Length	5090 mm
Wheel base	3034 mm
Kerb weight	1659 kg
Max. allowed weight	2283 kg

Additional information

Fuel tank capacity	85 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	03218707G

CarCheck.co.uk page 12/12