





report date: 2024-03-29

General information

| Make | FORD |
|---------------------|---------|
| Model | MUSTANG |
| Colour | White |
| Year of manufacture | 2006 |
| Gearbox | - |

Engine & fuel consumption

| Engine capacity | 4.000 cc |
|-----------------|----------|
| Fuel type | Petrol |



CarCheck.co.uk page 1/15




Internet history

Entry 1

Date 2021-12-31

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

| MOT expiry date | 2024-05-03 |
|--------------------|------------|
| MOT pass rate | 64 % |
| MOT passed | 16 |
| Failed MOT tests | 9 |
| Total advice items | 39 |
| Total items failed | 28 |

| MOT #25 | | 2023-05-04 17:56 |
|------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|------------------|
| MOT test | number | 253162784330 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-05-03 |
| Advice | Rear Tyre slightly damaged/cracking or perishing Both rears cracked (5.2.3 (d) (i | i)) |
| Advice Rear Axle deformed but serviceable axle has surface corrosion (live axle) (5.1.1 (a)) | | (a)) |
| Advice | Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (| i)) |

| MOT #24 | 2022-04-01 13:01 |
|--------------------------------------------------------------------------------------|------------------|
| MOT test number | 694329022409 |
| Result | ✓ Passed |
| Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) | |

| MOT #23 | 2022-03-28 15:01 |
|-------------------------------------------------------------------------------------------------|------------------|
| MOT test number | 223086840542 |
| Result | × Failed |
| Fail Side repeater missing Both nearside and offside (4.4.1 (a) (ii)) | |
| Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) | |
| Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| Advice Offside Rear Bumper mountings corroded but not likely to become detached (6.1.4 (a) (i)) | |

CarCheck.co.uk page 3/15



Result

AE55YV report date: 2024-03-29

MOT #22 2021-05-13 12:02

445714573253 **MOT** test number

✓ Passed Result

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #21 2020-01-16 17:19

MOT test number 570106930364

✓ Passed

Nearside Rear inner sill corroded **Advice**

Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Nearside Rear chassis corroded Advice

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear inner wheel arch corroded

Offside Rear inner sill corroded Advice

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Offside Rear chassis corroded

CarCheck.co.uk page 4/15



AE55YVT

report date: 2024-03-29

MOT #20 2020-01-15 11:22 141412293373 **MOT** test number Result × Failed **Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) Offside Rear inner sill corroded Advice Advice Offside Rear chassis corroded Fail Nearside Front Direction indicator incorrect colour (4.4.3 (a)) Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) Advice Nearside Rear inner sill corroded Offside Front Position lamp not working (4.2.1 (a) (ii)) Fail **Advice** Nearside Rear chassis corroded **Advice** Offside Rear inner wheel arch corroded Offside Front Direction indicator incorrect colour (4.4.3 (a)) Fail **Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

| MOT #19 | 2019-01-09 16:13 |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|
| MOT test number | 294269426848 |
| Result | ✓ Passed |
| Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) Minor Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i)) | |

| MOT #18 | 2018-01-03 16:51 |
|-----------------|------------------|
| MOT test number | 742353271015 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/15



MOT #17 2017-06-23 13:31

MOT test number 251008822051

Result ✓ Passed

Advice Nearside Suspension arm has slight play in a ball joint LIMITS!! (2.4.G.2)

Advice Rear n/s and o/s diff oil seals slight seepage

Advice Front Tyre worn close to the legal limit x2 (4.1.E.1)

Advice Nearside Play in steering rack inner joint(s)

Advice Brake pad(s) wearing thin front and rear (3.5.1g)

MOT #16 2016-06-07 11:39

MOT test number 327148762088

Result
✓ Passed

Advice Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

MOT #15 2015-06-05 10:18

MOT test number 716776755155

Result ✓ Passed

MOT #14 2014-06-23 11:27

MOT test number 897074974100

Result
✓ Passed

Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

Advice Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt

(2.2.C.1c)

Advice Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt

(2.2.C.1c)

MOT #13 2013-07-24 07:49

MOT test number 339515703457

Result ✓ Passed

CarCheck.co.uk page 6/15



MOT #10

AE55YVT

report date: 2024-03-29

2011-06-07 12:56

MOT #12 2013-07-23 15:09 **MOT test number** 415104503283 Result × Failed Fail Nearside Front Side repeater has less than 50% of the light sources illuminating (1.4.A.2c) Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3) Fail Fail Offside Rear Direction indicator not working (1.4.A.2c) Fail Offside Front Side repeater not working (1.4.A.2c) Exhaust has a major leak of exhaust gases (7.1.2) Fail Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

| MOT #11 | 2012-07-23 09:08 |
|-----------------------------------------------------------------------------------|------------------|
| MOT test number | 326045902283 |
| Result | ✓ Passed |
| Notice Nearside side repeater LEDs starting to fail Advice Exhaust noisy (7.1.4) | |

| MOT test number | 108828251173 |
|--------------------------------------------------------------------|------------------|
| Result | ✓ Passed |
| | |
| MOT #9 | 2011-06-07 08:59 |
| MOT test number | 299938751474 |
| Result | × Failed |
| Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f) | |
| Fail Registration plate lamp not working (1.1.C.1d) | |

CarCheck.co.uk page 7/15



MOT #8 2011-01-05 09:27

MOT test number 808635201092

Result X Failed

Advice Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

Pass with rectification Offside Front Front position lamp(s) not working (1.1.A.3b)

MOT #7 2011-01-05 09:27

MOT test number 135475001051

Result ✓ Passed

Advice Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

MOT #6 2010-01-21 11:48

MOT test number 882851520050

Result
✓ Passed

MOT #5 2009-12-10 16:47

MOT test number 474954549409

Result X Failed

Fail Nearside Direction indicators flashing more than 120 times a minute (1.4.A.2g)

Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

Fail Parking brake lever has no reserve travel (3.1.6b)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Fail Offside Direction indicators flashing more than 120 times a minute (1.4.A.2g)

Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Fail Emissions not tested (7.0)

CarCheck.co.uk page 8/15



MOT #4 2009-06-12 16:54

MOT test number 730083769124

Result

× Failed

Fail Rear fog lamp excessively damaged so that it is not visible from a reasonable distance (1.3.2d)

Fail Parking brake: efficiency below requirements (3.7.B.7)

MOT #3 2009-06-02 15:23

MOT test number 474683759128

Result X Failed

Fail Offside Rear fog lamp excessively damaged so that it is not visible from a reasonable distance (1.3.2d)

Fail Nearside rear parking brake recording little or no effort (3.7.B.6a)

Fail Rear Direction indicator incorrect colour (1.4.A.2f)

Fail Parking brake: efficiency below requirements (3.7.B.7)

MOT #2 2008-06-26 11:39

MOT test number 962328678180

Result
✓ Passed

MOT #1 2008-06-24 15:34

MOT test number 232036978471

Result X Failed

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

CarCheck.co.uk page 9/15



Tax & MOT check



Days left 307
MOT expiry date 3 May 2024

Full MOT history See MOT history

CarCheck.co.uk page 10/15



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/15



| Owner history | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------|
| For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report | |
| *************************************** | |
| | |
| *************************************** | |
| *************************************** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | , |
| Current registration | NIE |
| Plate since | |
| Current registration | NK SIN |
| Plate since | |
| | More info > |

CarCheck.co.uk page 12/15



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact into


More info >

CarCheck.co.uk page 13/15



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 26 |
| First mileage registration | 2006-01-01 |
| Last registration | 2023-05-04 |
| Complete history | See info |



| Registration #1 | 2006-01-01 | 11 mi |
|------------------|------------|-----------|
| Registration #2 | 2008-06-24 | 34.608 mi |
| Registration #3 | 2008-06-26 | 34.608 mi |
| Registration #4 | 2009-06-02 | 45.170 mi |
| Registration #5 | 2009-06-12 | 45.205 mi |
| Registration #6 | 2009-12-10 | 45.223 mi |
| Registration #7 | 2010-01-21 | 45.224 mi |
| Registration #8 | 2011-01-05 | 59.223 mi |
| Registration #9 | 2011-06-07 | 65.273 mi |
| Registration #10 | 2011-06-07 | 65.273 mi |
| Registration #11 | 2012-07-23 | 71.518 mi |
| Registration #12 | 2013-07-23 | 83.296 mi |
| Registration #13 | 2013-07-24 | 83.296 mi |
| Registration #14 | | 71.777 es |
| Registration #15 | | 11.777 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 11.777 es |
| Registration #18 | | 11.777 es |
| Registration #19 | | 11.777 es |
| Registration #20 | | 71.777 es |
| Registration #21 | | 11.777 es |
| Registration #22 | | 11.777 es |
| Registration #23 | | 11.777 es |
| Registration #24 | | 11.777 es |
| Registration #25 | | 11.777 es |
| Registration #26 | | 11.117 au |

CarCheck.co.uk page 14/15



·

Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 60482 | |
| 0501 | |
| 0566 | |
| 0567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Additional information

| Number of seats | 4 |
|-----------------|-----------|
| Engine number | NOT KNOWN |

CarCheck.co.uk page 15/15