



report date: 2024-03-29

General information

Make	CITROEN
Model	C3 BLUEHDI FEEL
Colour	Silver
Year of manufacture	2015
Top speed	114 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	74.3 mpg
Consumption extra urban	88.3 mpg
Consumption combined	83.1 mpg
CO2 emission	90 g/km
CO2 label	A





## Internet history

### Entry 2


Date	2021-01-29
Pictures	2
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://autoonline.co.uk)

### Entry 1

Date	2021-01-21
Pictures	15
Listing price	<a href="#">View report</a>



source: [yesauto.com](https://yesauto.com)



## MOT history

MOT expiry date	2024-12-23
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	8
Total items failed	14

## MOT #12 2023-12-12 15:25

MOT test number 686452462041

Result ✓ Passed

Next expiry date 2024-12-23

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Cracking and perishing inside edge!  
(5.2.3 (d) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Cracking and perishing inside edge!  
(5.2.3 (d) (ii))

## MOT #11 2022-12-22 17:38

MOT test number 486741773117

Result ✓ Passed

## MOT #10 2022-12-15 13:00

MOT test number 146925042573

Result ✗ Failed

**Advice** Items removed from driver's view prior to test

**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Fail** Offside Front Brake hose excessively twisted (1.1.12 (b) (ii))

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #9** 2021-12-23 14:45**MOT test number** 378365485717**Result** ✓ Passed**MOT #8** 2021-12-23 09:39**MOT test number** 608903468473**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Items removed from driver's view prior to test**Fail** Offside Front Headlamp aim not tested (4.1.2 (b))**MOT #7** 2020-12-24 09:17**MOT test number** 721388031346**Result** ✓ Passed**MOT #6** 2020-12-19 09:55**MOT test number** 225685052654**Result** ✗ Failed**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Exhaust system insecure (6.1.2 (a))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #5** 2020-06-26 13:00**MOT test number** 649744114792**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2020-06-25 12:23**MOT test number** 657677399791**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #3** 2019-06-14 13:36**MOT test number** 374552220235**Result** ✓ Passed**MOT #2** 2019-06-14 09:40**MOT test number** 396561254351**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #1** 2018-06-27 16:12**MOT test number** 205245471622**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
23 December 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	23 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2015-10-30
Last registration	2023-12-12
Complete history	<a href="#">See info</a>



Registration #1	2015-10-30	20 mi
Registration #2	2018-06-27	29.843 mi
Registration #3	2019-06-14	34.419 mi
Registration #4	2019-06-14	34.419 mi
Registration #5	2020-06-25	39.709 mi
Registration #6	2020-06-26	39.709 mi
Registration #7	2020-12-19	40.966 mi
Registration #8	2020-12-24	40.969 mi
Registration #9	2020-12-24	40.969 mi
Registration #10	2020-12-24	40.969 mi
Registration #11	2020-12-24	40.969 mi
Registration #12	2020-12-24	40.969 mi
Registration #13	2020-12-24	40.969 mi
Registration #14	2020-12-24	40.969 mi
Registration #15	2020-12-24	40.969 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1946 mm
Height	1540 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	1070 kg
Max. allowed weight	1610 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	JBHA0013600