



Y580CA

report date: 2024-03-29

General information

Make	MAZDA
Model	MX-5 S CONRAN-PLATINUM
Colour	Red
Year of manufacture	2001
Top speed	127 mph
0 - 60 mph	8.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	162 Nm at 4.500 rpm
Engine capacity	1.840 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.2 mpg
Consumption extra urban	40.4 mpg
Consumption combined	33.2 mpg
CO2 emission	205 g/km
CO2 label	K





MOT history

MOT expiry date	2021-02-19
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	12
Total items failed	17

MOT #23	2020-01-21 09:10
MOT test number	298574542109
Result	✓ Passed
Next expiry date	2021-02-19
Advice	Advanced corrosion on n/s rear wheel arch

MOT #22	2020-01-20 11:53
MOT test number	235066160551
Result	✗ Failed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Windscreen wiper does not clear the windscreen effectively o/s and n/s (3.4 (b) (ii))
Advice	Advanced corrosion on n/s rear wheel arch

MOT #21	2019-02-14 11:40
MOT test number	868925468716
Result	✓ Passed

**MOT #20** 2019-02-14 11:40**MOT test number** 188344649715**Result** ✗ Failed**Pass with rectification** Front Position lamp not working o/s and n/s (4.2.1 (a))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #19** 2018-02-15 10:39**MOT test number** 144035899100**Result** ✓ Passed**MOT #18** 2018-02-12 12:33**MOT test number** 378329680103**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Headlamp not working on main beam o/s and n/s (1.7.5a)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Front registration plate deteriorated (6.3.1d)**MOT #17** 2017-02-20 14:40**MOT test number** 834110980673**Result** ✓ Passed**Advice** General advanced corrosion

**MOT #16** 2017-02-20 14:40**MOT test number** 674109517549**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** General advanced corrosion**MOT #15** 2016-03-21 10:08**MOT test number** 958354023232**Result** ✓ Passed**MOT #14** 2016-03-17 10:22**MOT test number** 776442005667**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**MOT #13** 2015-03-26 16:24**MOT test number** 525615785046**Result** ✓ Passed**MOT #12** 2014-03-17 08:35**MOT test number** 508486674011**Result** ✓ Passed

**MOT #11** 2014-03-15 08:56**MOT test number** 348414974004**Result** ✗ Failed**Fail** Main beam 'tell-tale' not working (1.7.4c)**Fail** Headlamp not working on dipped beam (1.7.5a)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #10** 2013-02-14 13:43**MOT test number** 399835543065**Result** ✓ Passed**MOT #9** 2012-02-27 12:07**MOT test number** 705408452089**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2011-02-16 12:54**MOT test number** 206127041090**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2010-03-02 17:22**MOT test number** 104251660069**Result** ✓ Passed

**MOT #6** 2009-03-13 16:27**MOT test number** 640512979036**Result** ✓ Passed**MOT #5** 2009-03-12 09:59**MOT test number** 913851779039**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**MOT #4** 2009-03-11 15:05**MOT test number** 253040479015**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Advice** Nearside rear brake juddering slightly (3.7.A.5b)**Notice** Both front marker lights appear off white**MOT #3** 2008-02-25 11:40**MOT test number** 303476358061**Result** ✓ Passed**MOT #2** 2007-02-26 15:03**MOT test number** 120387657054**Result** ✓ Passed**MOT #1** 2006-02-20 12:00**MOT test number** 101041056468**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
17 December 2020

✕
MOT

Expired:
19 February 2021

Tax status	Expired at 17 December 2020
Days left	1229 days too late
MOT expiry date	19 February 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	Y58OCA
Plate since	2024-03-29
Current registration	Y58OCA
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2001-05-14
Last registration	2020-01-21
Complete history	See info



Registration #1	2001-05-14	13 mi
Registration #2	2006-02-20	28.162 mi
Registration #3	2007-02-26	36.083 mi
Registration #4	2008-02-25	45.028 mi
Registration #5	2009-03-11	53.497 mi
Registration #6	2009-03-12	53.509 mi
Registration #7	2009-03-13	53.531 mi
Registration #8	2010-03-02	62.415 mi
Registration #9	2011-02-16	68.645 mi
Registration #10	2012-02-27	74.964 mi
Registration #11	2013-02-14	79.263 mi
Registration #12	2014-03-15	87.138 mi
Registration #13	2015-03-15	95.013 mi
Registration #14	2016-03-15	102.888 mi
Registration #15	2017-03-15	110.763 mi
Registration #16	2018-03-15	118.638 mi
Registration #17	2019-03-15	126.513 mi
Registration #18	2020-01-21	134.388 mi
Registration #19	2020-01-21	134.388 mi
Registration #20	2020-01-21	134.388 mi
Registration #21	2020-01-21	134.388 mi
Registration #22	2020-01-21	134.388 mi
Registration #23	2020-01-21	134.388 mi
Registration #24	2020-01-21	134.388 mi

More info >



Dimensions & weight

Width	1680 mm
Height	1225 mm
Length	3975 mm
Wheel base	2265 mm
Kerb weight	1025 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	BP 428576