





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Grey
Year of manufacture	-
Top speed	92 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-12

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT test number 511282898648

Next expiry date 2021-09-29

MOT #11 2018-11-16 10:02

MOT test number 545318339829

Result
✓ Passed

MOT #10 2018-11-15 16:34

MOT test number 101380431827

Result X Failed

MAJOR Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MAJOR Windscreen washer provides insufficient washer liquid both front (3.5 (a))

MOT #9 2017-11-16 15:12

MOT test number 329751995204

Result ✓ Passed

MOT #8 2017-11-14 12:10

MOT test number 966337805627

Result X Failed

Fail Nearside Front brake caliper has restricted free movement (3.5.1k)

Fail Offside Front Front suspension has excessive movement at a wishbone pin or bush (2.5.A.1c)

Fail Nearside Front Front suspension has excessive movement at a wishbone pin or bush (2.5.A.1c)

MOT #7 2016-10-05 08:48

MOT test number 489801247102

Result
✓ Passed

Advice Both front lower suspension arms have play in rear bushes and replacement will be required soon

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #6 2016-10-05 08:48

MOT test number 913249114361

Result X Failed

Advice Both front lower suspension arms have play in rear bushes and replacement will be required soon

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

MOT #5 2015-10-09 00:00

MOT test number 215132371159

Result ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2014-10-02 12:17

MOT test number 148545874220

Result ✓ Passed

MOT #3 2013-10-08 12:48

MOT test number 357601783219

Result \(\sqrt{Passed} \)

Notice Wheel-trims fitted - retainers not checked

Notice Rear number plate delaminating

CarCheck.co.uk page 4/11



report date: 2024-03-29

MOT #2 2013-10-08 09:26 **MOT test number** 296211683208 Result **★** Failed **Notice** Handbrake travel becoming excessive Nearside Front Tyre has ply or cords exposed (4.1.D.1b) Fail Notice Front tyres worn on edges, low on tread Notice Wheel-trims fitted - retainers not checked Fail Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b) Notice Rear number plate delaminating **Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)

MOT #1	2012-09-21 14:38
MOT test number	628485962268
Result	✓ Passed

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NY
Plate since	
Current registration	NE UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-10-08
Last registration	2020-09-30
Complete history	See info



Registration #1	2009-10-08	26 mi
Registration #2	2012-09-21	10.281 mi
Registration #3	2013-10-08	30.519 mi
Registration #4	2013-10-08	30.520 mi
Registration #5	2014-10-02	45.984 mi
Registration #6	2015-10-09	62.611 mi
Registration #7	2016-10-05	78.975 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.00 44
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	★★★★ ★
Video	see crash video



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	3
CarChaels cands	no a o 11/11

CarCheck.co.uk page 11/11

Number of seats	4
Number of axles	2
Engine number	CHF 018451