



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI S/S ECOFLEX
Colour	Silver
Year of manufacture	2015
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	126 g/km
CO2 label	D





MOT history

MOT expiry date	2024-11-29
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	20
Total items failed	3

MOT #9	2023-11-30 16:20
MOT test number	931835690556
Result	✓ Passed
Next expiry date	2024-11-29
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #8	2023-11-30 16:20
MOT test number	456732378469
Result	✗ Failed
Pass with rectification	Stop lamp(s) all not working (4.3.1 (a) (iii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7**

2022-11-18 14:07

**MOT test number**

578051712794

**Result**

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Play in steering rack inner joint(s)

**MOT #6**

2022-11-18 14:07

**MOT test number**

353174226085

**Result**

✗ Failed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Play in steering rack inner joint(s)
- Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #5** 2021-10-26 12:44**MOT test number** 798341490971**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #4** 2020-10-20 10:24**MOT test number** 186414854807**Result** ✓ Passed**MOT #3** 2019-10-15 14:36**MOT test number** 649931044637**Result** ✓ Passed**MOT #2** 2018-10-23 09:44**MOT test number** 576894466018**Result** ✓ Passed**MOT #1** 2018-04-24 14:08**MOT test number** 808755671519**Result** ✓ Passed**Advice** Nearside front tyre worn on inner and outer surface



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
29 November 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	29 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VK15XNW
Plate since	2015-05-29
Current registration	 VK15XNW
Plate since	2015-05-29

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-05-14
Last registration	2023-11-30
Complete history	<a href="#">See info</a>



Registration #1	2015-05-14	16 mi
Registration #2	2018-04-24	75.452 mi
Registration #3	2018-10-23	78.170 mi
Registration #4	2019-10-15	84.141 mi
Registration #5	2020-10-20	88.466 mi
Registration #6	2020-10-20	88.466 mi
Registration #7	2020-10-20	88.466 mi
Registration #8	2020-10-20	88.466 mi
Registration #9	2020-10-20	88.466 mi
Registration #10	2020-10-20	88.466 mi

More info >



Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005564913 LN9